

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Interpretion ID: 44272 Main Street: EAST DV						Lesstien			
Intersection ID: 14373	Main Street: EAST_BV		Cross	Cross Street: LYNDHURST_AV				Location:	NE
ADA ID: ED11BA5509CB	Ramp T	Ramp Type: BlendTrans1			Initial Pass/Fail: Fail Overall Compliance: No				1.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description Data			Compliance Description Data		
		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	73.0	Yes	BlendTrans Slope (%)	3.6
		Two New Directional Ramps or		Yes	Ramp Width (in)	71.0	No	BlendTrans XSlope (%)	2.7
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
A Charles All A	8			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
and the second		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
Le the second		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
					X Walk 1 Direction	To SE		X Walk 2 Direction	N/A
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	YNDHURST AV	-			X Walk 1 Slope (%)	3.8		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	StopSign				X Walk 1 X Slope (%)	3.9		X Walk 2 X Slope (%)	N/A
Street 2 Name	. 0 N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A				Road Slope (%)	3.9		Clear Space?	N/A
					Road X Slope (%)	3.8	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

12.0