

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 13795 Main Street: DENBUR_DR Cross Street: LUSTERLEAF_HOLLY_RD Location: Ε Severity Score: **ADA ID: ED2B5E0F5267** Ramp Type: Perp Initial Pass/Fail: Pass **Overall Compliance: No** 0.25

Codes/Mitigation Info/Possible Solution



Street 1 Name	DENBUR DR
Stop Condition-Street 2	None
Street 2 Name	N/A
Stop Condition-Street 1	N/A

Possible Solutions:				
Remove & Replace Entire Ramp.				
Surveyor Notes:				
N/A				
N/A				
PROW/ADA:				
Not Found, R304.2.2-Perp, R304.3.2- Para, R304.5.3				
1 414, 1100 11010				

Total Cost:	\$ 1850.00

Field Measurements/Component Compliance							
Comp	liance Description	Data	Comp	liance Description	Data		
N/A	Ramp Length (in)	47.5	Yes	Ramp Slope (%)	5.5		
Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	2.6		
N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A		
N/A	Flare Slope LT (%)	3.2	N/A	Flare Slope RT (%)	7.8		
N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No		
Yes	Landing Length (in)	60.0	Yes	DWS Provided?	Yes		
Yes	Landing Width (in)	48.0	Yes	DWS Contrast?	Yes		
No	Landing Slope (%)	4.8	Yes	DWS Length (in)	24.0		
No	Landing X Slope (%)	3.5	Yes	DWS Full Width?	Yes		
N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset (in)	1.5		
N/A	Shared Landing?	Yes					
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	3.6		
Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	2.7		
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A		
	X Walk 1 Direction	To SW		X Walk 2 Direction	N/A		
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A		
	X Walk 1 Slope (%)	0.9		X Walk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	3.9		X Walk 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear Space?	Yes		
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A		
Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No		
	Obstruction Type			Storm Grate/Utility Type			
		N/A			N/A		
			Yes	Surface Condition? (G/P)	Good		
22 A							





