## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



		-	-	-					
Intersection ID: N/A	Main Street: MEADOW_VISTA_RD C			Street:	IVY_MEADOW_DR	Location:	S		
ADA ID: ED858AFDA6A7 Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	25	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
a surface of the		Possible Solutions:		Compliance Description			Data Compliance Description		
A AND REAL	A CARLEN PAR	Remove & Replace Curb Ramp W	/ith	N/A	Ramp Length (in)	68.0	No	Ramp Slope (%)	12.7
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	State of the second	Two New Directional Ramps or		Yes	Ramp Width (in)	53.0	Yes	Ramp XSlope (%)	0.0
A A A A A A A A A A A A A A A A A A A	Constanting of the second second	Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
E. Op	A STATE OF A			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	Op			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	12 AD			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	1 and the second second	- ····		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
81.0	All and the second			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	Martin and			N/A	Shared Landing?	N/A			
TEA COLOR	II'' TOP	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	IF ANN	R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Less -				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
1423	1 1 L				X Walk 1 Direction	To NE		X Walk 2 Direction	To NW
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	MEADOW VISTA RD	-			X Walk 1 Slope (%)	2.9		X Walk 2 Slope (%)	5.9
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	0.9		X Walk 2 X Slope (%)	0.8
Street 2 Name	IVY MEADOW RD			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	2.0	N/A	Clear Space?	N/A
					Road X Slope (%)	4.2	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A
1									

Yes Surface Condition? (G/P) Good

