

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

56.5

72.0

5.7

2.5

5.0

10.7

N/A

N/A

N/A

N/A

N/A

N/A

4.4

Intersection ID: 3313 Main Street: PROSPERITY CHURCH RD **Cross Street: OLD TIMBER RD** Location: SW

Overall Compliance: No Severity Score: 58.75 **ADA ID: EDBF84012569** Ramp Type: Combination1 Initial Pass/Fail: Fail

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Yes

Yes

No

Yes

No

N/A

N/A

N/A

N/A

N/A

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

Curb Slope (%)

Flare Traversable RT?

Ramp XSlope RT (%)

Data

54.0

73.0

17.9

2.1

24.0

40.5

N/A

N/A

N/A

N/A

N/A

N/A

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp XSlope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Flare Traversable LT?

Flare Type LT



Street 1 Name StopSign Stop Condition-Street 1 OLD TIMBER RD N/A Street 2 Name Stop Condition-Street 2 N/A Possible Solutions: Compliance Description N/A Remove & Replace Entire Ramp. Yes No No N/A No Surveyor Notes: N/A N/A N/A N/A N/A N/A PROW/ADA: N/A R304.5.1, R304.5.3, R304.3.2 N/A N/A N/A N/A N/A N/A



Total Cost:



1800.00

Landing X Slope (%) N/A N/A DWS Full Width? N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A Shared Landing? N/A **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No Painted X Walk2? N/A To N N/A X Walk 1 Direction X Walk 2 Direction X Walk 1 Width (in) N/A X Walk 2 Width (in) N/A X Walk 2 Slope (%) 3.5 N/A X Walk 1 Slope (%) X Walk 1 X Slope (%) 9.7 X Walk 2 X Slope (%) N/A N/A Ramp inside XWalk1? N/A N/A Ramp inside XWalk2? N/A Road Slope (%) N/A Clear Space? N/A Road X Slope (%) N/A N/A Clear Space to XWalk (in) N/A N/A Any Obstruction? N/A **Obstruction Type** N/A N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A Yes Surface Condition? (G/P) Good

