cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10033071 Main Street: NORTH_COMMUNITY_HOUSE_@Doss Street: N/A									Location:	NE
ADA ID: EE2623252BB7	Ramp Ty	Ramp Type: Perp				ail: Fail Overall (o Severity Score:	33.75		
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
	10 15	Possible Solutions:					liance Description	Data		
	· · · · ·	Remove & Replace	e Entire Ramp.	Ν	I/A	Ramp Length (in)	60.0	No	Ramp Slope (%)	13.1
	a Por			١	lo	Ramp Width (in)	47.5	Yes	Ramp XSlope (%)	1.6
	14 A.			N	I/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
Contraction and a	Little .			١	I/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
and the second	and the second s			١	I/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	FER-PR			N	I/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
and a state of the	A STATISTICS	Surveyor Notes:		N	I/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	A	N/A		N	I/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
North				١	I/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
COMMUNITY HOU	the second se			١	I/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
HOUL TOUR				N	I/A	Shared Landing?	N/A			
And Anna and		PROW/ADA:		N	I/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
A STATE OF A	1990 - Carlos	Not Found, R304.	5.1. R304.2.2	N	I/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
the second second	- Martin		,	N	I/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
117 30 2001 1	C. Top					X Walk 1 Direction	To NW		X Walk 2 Direction	N/A
	and a state of			1	I/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	ENTRANCE					X Walk 1 Slope (%)	1.1		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None					X Walk 1 X Slope (%)	1.9		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N	I/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A			-		Road Slope (%)	N/A		Clear Space?	N/A
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				,	N/A	Any Obstructions?	N/A		Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$ 1	850.00		Obstruction Type			Storm Grate/Utility Type	
			ΨΙ				N/A		clothi Grato, Guilty Type	N/A
1							13/A			11/7

Yes Surface Condition? (G/P)

Good

