

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 11666 Main St	ersection ID: 11666 Main Street: DENVER_AV		: MULBERRY_CHURCH	Location:	SW		
ADA ID: EE5480A173D1 Ramp 1	3D1 Ramp Type: Combination1Diag		tial Pass/Fail: Fail Overall Compliance		No Severity Score:	0	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance				
	Possible Solutions:	Comp	Compliance Description		Data Compliance Description		
	Remove & Replace Curb Ramp Wi		Ramp Length LT (in)	41.0 N/A		<u>Data</u> 30.0	
	Two New Directional Ramps or Equivalent.	Yes	Ramp Width LT (in)	62.0 Yes	,	62.0	
		Yes	Ramp Slope LT (%)	0.5 Yes		5.6	
		Yes	Ramp XSlope LT (%)	1.5 Yes		2.0	
	er.	N/A	Ramp Length (in)	48.0 Yes	Ramp Slope (%)	6.2	
		No	Ramp Width (in)	47.0 No	Ramp XSlope (%)	2.2	
	Surveyor Notes:	N/A	Flare Type LT	N/A N/A	Flare Type RT	N/A	
	LT RP < 5%	N/A	Flare Slope LT (%)	N/A N/A	Flare Slope RT (%)	N/A	
A TA		N/A	Flare Traversable LT?	N/A N/A	Flare Traversable RT?	N/A	
		N/A	Landing Length (in)	N/A N/A	DWS Provided?	N/A	
		N/A	Landing Width (in)	N/A N/A	DWS Contrast?	N/A	
	PROW/ADA:	N/A	Landing Slope (%)	N/A N/A	DWS Length (in)	N/A	
	Not Found, R304.5.1, R304.5.3	N/A	Landing X Slope (%)	N/A N/A		N/A	
		N/A	Landing Curb? (Y/N)	N/A N/A	DWS Offset (in)	N/A	
		N/A	Shared Landing?	N/A			
		N/A	Gutter Ponding?	N/A N/A	Gutter Slope (%)	N/A	
Street 1 Name StopSign		N/A	Gutter Lip Ht (in)	N/A N/A	Gutter X Slope (%)	N/A	
Stop Condition-Street 1 DENVER AV		N/A	Painted X Walk1?	No N/A	Painted X Walk2?	No	
Street 2 Name None			X Walk 1 Direction	To E	X Walk 2 Direction	To N	
Stop Condition-Street 2 MULBERRY CHURCH RD			X Walk 1 Width (in)	N/A	X Walk 2 Width (in)	N/A	
			X Walk 1 Slope (%)	3.7	X Walk 2 Slope (%)	2.0	
			X Walk 1 X Slope (%)	1.7	X Walk 2 X Slope (%)	1.3	
	Total Cost: \$ 320	0.00 N/A	Ramp inside XWalk1?	N/A N/A		N/A	
			Road Slope (%)	0.3	Clear Space?	N/A	
			Road X Slope (%)	3.8 N/A	Clear Space to XWalk (in)	N/A	
		SHEET STATE		N/A	Any Obstruction?	N/A	
		The second second			Obstruction Type		
		CONTRACTOR OF				N/A	
	and the second s			N/A	Storm Grate/Utility Hazard?	N/A	
		The second			Storm Grate/Utility Type	11/74	

Yes Surface Condition? (G/P) Good Curb Slope (%) 9.5