cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10036062	Main Str	Main Street: RIVERGATE_PY				N/A	Location:	N		
ADA ID: EF5BBE34CCF7		Ramp Type: Perp			s/Fai	il: Fail Overall (o Severity Score:	10		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Co						
Possible Solutions:								liance Description	Data	
	10 01	Remove & Replace E	ntiro Ramn	_		Ramp Length (in)	95.0	Yes	Ramp Slope (%)	6.7
X CAA			nine Ramp.	N		Ramp Width (in)	42.0	No	Ramp XSlope (%)	2.2
	C. C. SON			N		Flare Type LT	N/A		Flare Type RT	N/A
L'UC I Barth I				N		Flare Slope LT (%)	N/A		Flare Slope RT (%)	N/A
5. B				N		Flare Traversable LT?	N/A		Flare Traversable RT?	N/A
the second second	M. 4.			N		Landing Length (in)	N/A		DWS Provided?	N/A
	ANTIM	Surveyor Notes:		N		Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
SUER GA	and the second second	N/A		N	/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
A A A A A A A A A A A A A A A A A A A	and the second second	10/4		N		Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
a the second	the state of			N		Landing Curb? (Y/N)	N/A		DWS Offset (in)	N/A
и				N	/A	Shared Landing?	N/A			
	A A A A	PROW/ADA:		N		Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	1	Not Found, R304.5.1	R304 5 3	N	Α	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	10 10 10		, 1004.3.3	N		Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
Sill L.	A. VO					X Walk 1 Direction	To SW		X Walk 2 Direction	N/A
	The and			N	/Α	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	RIVERGATE PY	J				X Walk 1 Slope (%)	3.8		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None					X Walk 1 X Slope (%)	0.9		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N		Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N	/A	Any Obstructions?	N/A		Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$ 1	850.00	-	Obstruction Type			Storm Grate/Utility Type	
			÷				N/A			N/A

Yes Surface Condition? (G/P)

Good

