

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 12201 Main Street: HIGHLAND_AV Cross Street: MARKET_ST Location: E

ADA ID: EF67B3136DDD Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 35

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name MARKET ST
Stop Condition-Street 2 None
Street 2 Name N/A
Stop Condition-Street 1 N/A

Remove & Replace Entire Ramp.								
Surveyor Notes:								
•								
N/A								
PROW/ADA:								
Not Found, R304.5.1, R304.2.2,								
R304.5.3								

				t _p -	Y.
	111				
	1	- 7	and the second		
S					
*	w.	一种	William		1

Total Cost:



1850.00

Compliance Description Date Compliance Description									
	liance Description	Data		liance Description	Data				
N/A	Ramp Length (in)	60.5	No	Ramp Slope (%)	13.3				
No	Ramp Width (in)	47.0	No	Ramp XSlope (%)	4.9				
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A				
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A				
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A				
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A				
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A				
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A				
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A				
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A				
N/A	Shared Landing?	N/A							
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A				
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A				
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A				
	X Walk 1 Direction	To W		X Walk 2 Direction	N/A				
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A				
	X Walk 1 Slope (%)	1.8		X Walk 2 Slope (%)	N/A				
	X Walk 1 X Slope (%)	3.8		X Walk 2 X Slope (%)	N/A				
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A				
	Road Slope (%)	N/A	N/A	Clear Space?	N/A				
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A				
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A				
	Obstruction Type			Storm Grate/Utility Type					
		N/A			N/A				
			Yes	Surface Condition? (G/P)	Good				
100									