

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 11841	Main Str	eet: E_18TH_ST	Cross S	Street.	HARRILL_ST			Location:	N	
ADA ID: EFCC73DF9ADE Ramp Type: Directional1			Initial P	Initial Pass/Fail: Pass Overall Compliance: No				o Severity Score:	0	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	24 / 1A	Possible Solutions:		Compliance Description Data			Compliance Description		Data	
	8 18/	Remove & Replace Entire Ramp).	N/A	Ramp Length (in)	75.0	Yes	Grade Break?	Yes	
1 - APRIL - 1 Com 1	21 Maria			Yes	Ramp Width (in)	56.5	Yes	Grade Break Slope (%)	3.1	
	105			Yes	Ramp Slope (%)	2.1	Yes	Grade Break XSlope (%)	1.1	
	11 1 5			Yes	Ramp XSlope (%)	1.3				
8/1	and a	1		Yes	Flare Type LT	N/A	Yes	Flare Type RT	N/A	
A A A A A A A A A A A A A A A A A A A	and the			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
300 3 1 1 A		Surveyor Notes:		N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No	
BER BURNER		RP SL < 5%		Yes	Landing Length (in)	58.5	Yes	DWS Provided?	Yes	
	- Stand			Yes	Landing Width (in)	58.5	Yes	DWS Contrast?	Yes	
E C	S LON			Yes	Landing Slope (%)	0.2	Yes	DWS Length (in)	24.0	
	SUNCES.			Yes	Landing X Slope (%)	0.9	Yes	DWS Full Width?	Yes	
	10.00	PROW/ADA:		N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset LT (in)	1.5	
4 10 3	2 and	Not Found, R302.7		N/A	Shared Landing?	Yes	Yes	DWS Offset RT (in)	22.5	
	1- 2	,		No	Gutter Ponding?	Yes	Yes	Gutter Slope (%)	3.8	
MALIN MALIN	A BARRADO			Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.2	
15/ 6 4 195	1 44			N/A	Painted X Walk1?	No		Road Slope (%)	3.8	
Street 1 Name	HARRILL ST				X Walk 1 Direction	To SE		Road X Slope (%)	1.2	
Stop Condition-Street 1	None				X Walk 1 Width (in)	N/A		Clear Space?	Yes	
Street 2 Name	N/A				X Walk 1 Slope (%)	3.8	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	1.2	Yes	Storm Grate/Utility Hazard?	No	
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
				Yes	Any Obstructions?	No			N/A	
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
						N/A	No	Curb Slope (%)	19.7	

