## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: N/A	Main Str	Cross Street: N/A				Location:	N	
ADA ID: F0018E348465	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	22.5
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:				liance Description	Data		
		Remove & Replace Entire Ramp	_			1	Ramp Slope (%)	8.4
The state of the s			No	1 0 ( )	,		Ramp XSlope (%)	3.2
3 8 3			N/A	1 ( )		N/A	Flare Type RT	N/A
			N/A	51	%) <b>N/A</b>	N/A	Flare Slope RT (%)	N/A
A INTERNET	Sama and Cont		N/A		,	N/A	Flare Traversable RT?	N/A
5.		-	N/A				DWS Provided?	N/A
		Surveyor Notes:	N/A	0 0 0	,		DWS Contrast?	N/A
A ANDINI		N/A	N/A	6 (	,	N/A	DWS Length (in)	N/A
	- Part		N/A	6 I V		N/A	DWS Full Width?	N/A
A DESCRIPTION OF THE REAL PROPERTY OF THE REAL PROP	144		N/A	5 1			DWS Offset (in)	N/A
A 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4			N/A				()	
1 marine Martin		PROW/ADA:	N/A	8		N/A	Gutter Slope (%)	N/A
A los all and the	- and	R304.5.1, R304.2.2, R304.5.3	N/A	- 9		N/A	Gutter X Slope (%)	N/A
Edia Marine Marine	- ALING AL	R304.3.1, R304.2.2, R304.3.3	N/A	1 ( )		N/A	Painted X Walk2?	N/A
Viet and the second				X Walk 1 Directio			X Walk 2 Direction	N/A
			N/A			N/A	X Walk 2 Width (in)	N/A
Street 1 Name	GLENBURN LN	1	107	X Walk 1 Slope (	,		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None			X Walk 1 X Slope	,		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A		N/A	•	· · /	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A			Road Slope (%)	N/A	N/A	Clear Space?	N/A
	N/A			Road X Slope (%)		N/A	Clear Space to XWalk (in)	N/A
			N//		,		Storm Grate/Utility Hazard?	N/A N/A
		Total Cost: \$	1850.00	Obstruction Type			Storm Grate/Utility Type	11/2
		10tai 00st. 🛛 🗘	1000.00	Obstruction Type	, N/A		Storm Grate/Ounty Type	N/A
					IN/A	1		IN/A

