## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

Curb Slope (%)

8.6

Intersection ID: 15063	Main Str	eet: DUNN_AV	Cross	Street:	ORANGE_ST	Location:	SE		
ADA ID: F15016DFF258		 Ramp Type: ParaDiag			Initial Pass/Fail: Fail Overall Compliance: No				
Codes/Mitigation Info/Possible Solution				nitial Pass/Fail: Fail Overall Compliance: No Severity Score: 12.5 Field Measurements/Component Compliance					
	T.	Possible Solutions:					Compliance Description Data		
		Remove & Replace Curb Ramp	With	N/A	Ramp Length LT (in)	43.0	N/A	Ramp Length RT (in)	41.0
		Two New Directional Ramps or		Yes	Ramp Width LT (in)	72.0	Yes	Ramp Width RT (in)	72.0
		Equivalent.		No	Ramp Slope LT (%)	8.7	Yes	Ramp Slope RT (%)	1.6
A LAND	A Carlos and a car			Yes	Ramp XSlope LT (%)	1.2	Yes	Ramp XSlope RT (%)	1.5
	1. 36 XONO			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
6 C				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		Surveyor Notes:		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		RT RP < 5%		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
B B D D D D D D D D D D D D D D D D D D				N/A	Shared Landing?	N/A			
LI SH				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		PROW/ADA:		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
S I I I I I I I I I I I I I I I I I I I		R304.3.2		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To NE		X Walk 2 Direction	To NW
	A YAN			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
11 El martin					X Walk 1 Slope (%)	1.2		X Walk 2 Slope (%)	3.6
Street 1 Name	DUNN AV				X Walk 1 X Slope (%)	0.8		X Walk 2 X Slope (%)	2.8
Stop Condition-Street 1	None			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Street 2 Name	ORANGE ST				Road Slope (%)	3.6	N/A	Clear Space?	N/A
Stop Condition-Street 2	StopSign				Road X Slope (%)	2.1	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
					Obstruction Type			Storm Grate/Utility Type	
		Total Cost: \$	3200.00			N/A			N/A
							Yes	Surface Condition? (G/P)	Good

