cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 3273	3273 Main Street: BILLINGHAM_DR			Cross	Street:	PROSPERITY_CHUR	Location:	NE			
ADA ID: F1D0296C48	D: F1D0296C4806 Ramp Type: ParaDiag			Initial	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	13.75	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
		Possible Solutions:		Compliance Description Data			Compliance Description		Data		
		Remove & Replace Curb	Ram	np With	N/A	Ramp Length LT (in)	60.0	N/A	Ramp Length RT (in)	67.0	
22 1 131		Two New Directional Ramp Equivalent.		•	Yes	Ramp Width LT (in)	71.0	Yes	Ramp Width RT (in)	71.0	
21 1 18					No	Ramp Slope LT (%)	9.5	Yes	Ramp Slope RT (%)	4.9	
					Yes	Ramp XSlope LT (%)	1.6	No	Ramp XSlope RT (%)	2.6	
	1. Just and				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	177 × (1)				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
		Surveyor Notes:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
	<u>ь</u>	RT RP < 5%			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
ETHINGS FOR					N/A	Shared Landing?	N/A				
					N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
		PROW/ADA:			N/A	Gutter Lip Ht (in)	1.5	N/A	Gutter X Slope (%)	N/A	
R304.3.2, R304.5.3					N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
						X Walk 1 Direction	To W		X Walk 2 Direction	To S	
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A		
					X Walk 1 Slope (%)	3.7		X Walk 2 Slope (%)	1.6		
Street 1 Name	PROSPERITY CHURCH RD					X Walk 1 X Slope (%)	0.2		X Walk 2 X Slope (%)	4.1	
Stop Condition-Street 1	None				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Street 2 Name	BILLINGHAM DR					Road Slope (%)	1.6	N/A	Clear Space?	N/A	
Stop Condition-Street 2	StopSign					Road X Slope (%)	3.5	N/A	Clear Space to XWalk (in)	N/A	
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
						Obstruction Type			Storm Grate/Utility Type		
		Total Cost:	\$	3200.00			N/A			N/A	
								Yes	Surface Condition? (G/P)	Good	







N/A

Curb Slope (%)

17.6