cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 45496	6 Main Street: COTTON_PRESS_RD			Cross Street: COTTON_STAND_RD				Location:	SW
ADA ID: F248221A82CD	Ramp Ty	Ramp Type: PerpDiag			ail: Fail Overall	o Severity Score:	12.5		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Descriptio		Data Compliand		ance Description	Data
		Remove & Replace Curb Ra	mp With	N/A	Ramp Length (in)	84.0	No	Ramp Slope (%)	9.6
		Two New Directional Ramps	•	Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	0.8
	Er III In	Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
CAR PAR	N/5/ 10			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	S ANN			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
the second se	57 B B	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
				N/A	Shared Landing?	N/A		()	
- 80 P /	100	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Not Found, K304.2.2				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To SE		X Walk 2 Direction	To NE
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	COTTON PRESS RD	-			X Walk 1 Slope (%)	3.3		X Walk 2 Slope (%)	0.7
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	0.7		X Walk 2 X Slope (%)	0.4
Street 2 Name	COTTON STAND RD			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	1.5	N/A	Clear Space?	N/A
					Road X Slope (%)	0.0	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	0.0 N/A		Storm Grate/Utility Hazard?	N/A
		Total Cost:	3200.00		Obstruction Type			Storm Grate/Utility Type	
		• • • • • • • • • •				N/A			N/A
									10/5

Yes Surface Condition? (G/P)

Good

