## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 28115 Main Street: DARBY_CHASE_DR			Cross	Cross Street: PROVIDENCE_GREEN_CT				Location:	NW
ADA ID: F2D5BC0B49	BC0B49B1 Ramp Type: BlendTrans1			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	35
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
and the second		Possible Solutions:		Compliance Description Data Compliance			Comp	Compliance Description Data	
		Remove & Replace Curb Ram	p With	N/A	Ramp Length (in)	46.0	Yes	BlendTrans Slope (%)	3.7
and the second s		Two New Directional Ramps or Equivalent.		No	Ramp Width (in)	29.0	Yes	BlendTrans XSlope (%)	0.4
	E I			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	B. A			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
Ter	R AND			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	He come			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	1	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
To a the Aller Car		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
PROW/ADA: Not Found, R304.5.1				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
					X Walk 1 Direction	To E		X Walk 2 Direction	N/A
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	PROVIDENCE GREEN CT	-			X Walk 1 Slope (%)	4.5		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	StopSign				X Walk 1 X Slope (%)	0.6		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A				Road Slope (%)	0.6		Clear Space?	N/A
					Road X Slope (%)	4.5	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A		Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A
							1		







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

18.5