

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 9796Main Street:BARRINGTON_DRCross Street:MONTEGO_DRLocation:NWADA ID: F30BBFFC570DRamp Type:PerpInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:22.5

Codes/Mitigation Info/Possible Solution



Street 1 Name	MONTEGO DR
Stop Condition-Street 2	None
Street 2 Name	N/A
Ston Condition-Street 1	N/A

1 OSSIDIE SOIGLIOII	
Possible Solutions:	<u>c</u>
Remove & Replace Entire Ramp.	N
•	N
	N
	N
	N
	N
Surveyor Notes:	N
N/A	N
	N
	N
	N
PROW/ADA:	N
Not Found, R304.5.1, R304.2.2	N
,	N
	N

Total Cost:	\$ 1850.00

Field Measurements/Component Compliance							
Compl	liance Description	Data	Comp	liance Description	Data		
N/A	Ramp Length (in)	28.0	No	Ramp Slope (%)	10.5		
No	Ramp Width (in)	47.5	Yes	Ramp XSlope (%)	3.3		
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
N/A	Shared Landing?	N/A					
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	0.5	N/A	Gutter X Slope (%)	N/A		
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A		
	X Walk 1 Direction	To SE		X Walk 2 Direction	N/A		
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A		
	X Walk 1 Slope (%)	3.5		X Walk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	4.6		X Walk 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear Space?	N/A		
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A		
	Obstruction Type			Storm Grate/Utility Type			
		N/A			N/A		
			Yes	Surface Condition? (G/P)	Good		
The state of the s							





