

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 15839	Main Str	Main Street: DORCHESTER_PL			Cross Street: SEDGEFIELD_RD				NW
								Location:	
ADA ID: F36D74BFBD69	DA ID: F36D74BFBD69 Ramp Type: Directional1		Initial	Initial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	13.75	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
A A A		Possible Solutions:		Compliance Description		Data Compliance Description		Data	
	X / Xx	Remove & Replace Entire Ra	np.	N/A	Ramp Length (in)	65.0	N/A	Grade Break?	N/A
	5	-	-	Yes	Ramp Width (in)	48.0	N/A	Grade Break Slope (%)	0.0
	15 Contraction			No	Ramp Slope (%)	9.3	N/A	Grade Break XSlope (%)	0.0
The Arter of				No	Ramp XSlope (%)	4.5			
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
34 AT 37	Aler Ja			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
SEDCERTED O		Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
		N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
				N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
and the second second				N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
	The second second			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
	1 North 1	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
A P A	1 and the	R304.2.2, R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
North and Alle	- And Makes			N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
The second	P PA IN			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No		Road Slope (%)	0.6
Street 1 Name	DORCHESTER PL				X Walk 1 Direction	To E		Road X Slope (%)	3.5
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A				X Walk 1 Slope (%)	0.6	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	3.5	N/A	Storm Grate/Utility Hazard?	N/A
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
				N/A	Any Obstructions?	N/A			N/A
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	2.9

