

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: 12248 Main Street: E\_8TH\_ST Cross Street: N\_BREVARD\_ST Location:

**Overall Compliance: No** ADA ID: F381DF9DF6EE Ramp Type: Perp Initial Pass/Fail: Fail Severity Score: 21.25

## Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name E8THST Stop Condition-Street 2 StopSign Street 2 Name N/A Stop Condition-Street 1 N/A

Possible Solution	
Possible Solutions:	Con
Remove & Replace Entire Ramp.	N/A
	No
	N/A
	N/A
	N/A
	N/A
Surveyor Notes:	N/A
SLOPES VERIFIED & MATCH	N/A
	N/A
	N/A
	N/A
PROW/ADA:	N/A
R304.5.1, R304.2.2	N/A
·	N/A
	N/A
	N/A

TROWADA.		
R304.5.1, R304.2.2		N/
		N/
Total Cost:	\$ 1850.00	

	Fleid Measurements/Component Compilance							
Compliance Description		Data	Data Compliance Description		Data			
N/A	Ramp Length (in)	71.0	No	Ramp Slope (%)	8.7			
No	Ramp Width (in)	40.0	Yes	Ramp XSlope (%)	0.1			
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A			
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A			
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A			
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A			
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A			
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A			
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A			
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A			
N/A	Shared Landing?	N/A						
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A			
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A			
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A			
	X Walk 1 Direction	To SW		X Walk 2 Direction	N/A			
N/A	X Walk 1 Width (in)	123.0	N/A	X Walk 2 Width (in)	N/A			
	X Walk 1 Slope (%)	2.1		X Walk 2 Slope (%)	N/A			
	X Walk 1 X Slope (%)	0.2		X Walk 2 X Slope (%)	N/A			
N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A			
	Road Slope (%)	N/A	N/A	Clear Space?	N/A			
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A			
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A			
	Obstruction Type			Storm Grate/Utility Type				
		N/A			N/A			
			Yes	Surface Condition? (G/P)	Good			
44	dieta A							





