## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 8599	Main Street: HATERAS AV			Stroot:	IRMA_ST	Location:	SW		
ADA ID: F3B8B963E2F3	A ID: F3B8B963E2F3 Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	21.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	1	Possible Solutions:		Compliance Description			Data Compliance Description		Data
		Remove & Replace Entire Ramp	).	N/A	Ramp Length (in)	71.5	Yes	Ramp Slope (%)	5.5
				No	Ramp Width (in)	47.0	No	Ramp XSlope (%)	5.4
and the second second				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	Card and a			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
Adde the set of the	A Paral P			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
MATERAS AV				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
ALLE IS L.		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	m 1			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
and the second	and the second s			N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
All and	The There is	Not Found, R304.5.1, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
					X Walk 1 Direction	To N		X Walk 2 Direction	N/A
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	HATERAS AV				X Walk 1 Slope (%)	5.5		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	3.6		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

