cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 16512 Main Street: AMITY_PL				Cross Street: ELM_FOREST_DR				Location:	SE
ADA ID: F44479AC31BC				Initial Pass/Fail: Fail Overall Compliance: No					8.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
Possible Solutions:				Compliance Description Data Compliance Description Data					
			\A/:+la	N/A	Ramp Length (in)	45.0	Yes	BlendTrans Slope (%)	0.4
		Remove & Replace Curb Rar Two New Directional Ramps	•	N/A No	Ramp Width (in)	45.0 38.0	Yes	BlendTrans XSlope (%)	0.4 1.0
		Equivalent.	01	N/A	Flare Type LT	38.0 N/A	N/A	Flare Type RT	N/A
				N/A N/A	•••	N/A	N/A		N/A N/A
					Flare Slope LT (%)			Flare Slope RT (%)	
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	PL ,			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	A CONTRACTOR	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	N/A				
	the U.	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
B B B B B B B B B B B B B B B B B B B	- 1013	Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	the Martin			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
				X Walk 1 Direction	To N		X Walk 2 Direction	To W	
And the second second	Carlos Antonio				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	AMITY PL				X Walk 1 Slope (%)	5.6		X Walk 2 Slope (%)	10.2
Stop Condition-Street 1	None				X Walk 1 X Slope (%)	6.2		X Walk 2 X Slope (%)	4.5
Street 2 Name	ELM FOREST DR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	StopSign				Road Slope (%)	1.8		Clear Space?	N/A
	. •				Road X Slope (%)	13.0	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
					<i>,</i> ,	N/A		, , , , , , , , , , , , , , , , , , ,	N/A
1						10/4			1975







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

7.4