cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 29997 Main St	997 Main Street: MOORGATE_RD		Cross Street: WINDING_RIVER_DR			Location:	SE	
ADA ID: F4B93A4D4754 Ramp Type: PerpDiag		Initial Pass	itial Pass/Fail: Pass Overall Compliance: No			o Severity Score:	7.5	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance Description Data		Compliance Description		Data	
to the second se	Remove & Replace Curb Ramp Wi	ith N/A	Ramp Length (in)	73.0	Yes	Ramp Slope (%)	6.5	
	Two New Directional Ramps or	Yes	Ramp Width (in)	52.0	Yes	Ramp XSlope (%)	1.3	
	Equivalent. Remove & Replace	N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A	
	Gutter.	N/A	Flare Slope LT (%)	5.6	Yes	Flare Slope RT (%)	5.6	
		N/A	Flare Traversable LT?	Yes	N/A	Flare Traversable RT?	Yes	
		Yes	Landing Length (in)	48.0	Yes	DWS Provided?	Yes	
	Surveyor Notes:	Yes	Landing Width (in)	52.0	Yes	DWS Contrast?	Yes	
	N/A	No	Landing Slope (%)	2.6	Yes	DWS Length (in)	25.5	
		Yes	Landing X Slope (%)	0.4	No	DWS Full Width?	No	
		N/A	Landing Curb? (Y/N)	No	No	DWS Offset (in)	3.0	
		N/A	Shared Landing?	No				
	PROW/ADA:	Yes	Gutter Ponding?	No	No	Gutter Slope (%)	8.5	
	Not Found, R304.2.2-Perp, R304.3.	.2- Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	0.2	
	Para, R305.1.4, R305.2, R304.5.4	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
			X Walk 1 Direction	To N		X Walk 2 Direction	To W	
		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name WINDING RIVER DR			X Walk 1 Slope (%)	2.5		X Walk 2 Slope (%)	2.5	
Stop Condition-Street 2 None			X Walk 1 X Slope (%)	2.2		X Walk 2 X Slope (%)	0.2	
Street 2 Name MOORGATE RD		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1 StopSign			Road Slope (%)	2.6	N/A	Clear Space?	Yes	
			Road X Slope (%)	1.3	N/A	Clear Space to XWalk (in)	N/A	
		Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No	
	Total Cost: \$ 39	50.00	Obstruction Type			Storm Grate/Utility Type		
				N/A			N/A	

Yes Surface Condition? (G/P)

Good

