

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

10.0

3.7

N/A

N/A

N/A

Intersection ID: 26384 Main Street: BEVINGTON_PL **Cross Street: ELM LN** Location: NE **Overall Compliance: No ADA ID: F56A0FDBE1EE** Ramp Type: Perp Initial Pass/Fail: Fail Severity Score: 13.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

48.0 No

N/A N/A

No

N/A

N/A

Data

59.0

N/A

N/A

Compliance Description

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

Flare Traversable RT?

Flare Type RT



| Street 1 Name | ELM LN |
|-------------------------|--------|
| Stop Condition-Street 2 | Signal |
| Street 2 Name | N/A |
| Stop Condition-Street 1 | N/A |

| Possible Solutions: | Comp | liance | Description |
|-------------------------------|------|--------|------------------|
| Remove & Replace Entire Ramp. | N/A | Ram | p Length (in) |
| · | Yes | Ram | p Width (in) |
| | N/A | Flare | Type LT |
| | N/A | Flare | Slope LT (%) |
| | N/A | Flare | Traversable LT |
| | N/A | Land | ing Length (in) |
| Surveyor Notes: | N/A | Land | ing Width (in) |
| N/A | N/A | Land | ing Slope (%) |
| | N/A | Land | ing X Slope (%) |
| | N/A | Land | ing Curb? (Y/N) |
| | N/A | Share | ed Landing? |
| PROW/ADA: | N/A | Gutte | er Ponding? |
| Not Found, R304.2.2, R304.5.3 | N/A | Gutte | er Lip Ht (in) |
| , | N/A | Paint | ed X Walk1? |
| | | X Wa | lk 1 Direction |
| | N/A | X Wa | ılk 1 Width (in) |
| | | X Wa | ılk 1 Slope (%) |
| | | X Wa | ılk 1 X Slope (% |
| | N/A | Ram | p inside XWalk1 |
| | | Road | Slope (%) |
| | | | |

| 1 1 1 |
|-------|
| # |
| |
| |



| | | | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
|-------------------------------|----|---------|-----|----------------------|-------|-----|-----------------------------|------|
| Surveyor Notes: | | | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| N/A | | | N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| | | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| | | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| | | | N/A | Shared Landing? | N/A | | | |
| PROW/ADA: | | | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| Not Found, R304.2.2, R304.5.3 | | | N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A |
| | | | N/A | Painted X Walk1? | Yes | N/A | Painted X Walk2? | N/A |
| | | | | X Walk 1 Direction | To W | | X Walk 2 Direction | N/A |
| | | | N/A | X Walk 1 Width (in) | 120.0 | N/A | X Walk 2 Width (in) | N/A |
| | | | | X Walk 1 Slope (%) | 5.9 | | X Walk 2 Slope (%) | N/A |
| | | | | X Walk 1 X Slope (%) | 0.6 | | X Walk 2 X Slope (%) | N/A |
| | | | N/A | Ramp inside XWalk1? | Yes | N/A | Ramp inside XWalk2? | N/A |
| | | | | Road Slope (%) | N/A | N/A | Clear Space? | N/A |
| | | | | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A |
| | | | N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| Total Cost: | \$ | 1850.00 | | Obstruction Type | | | Storm Grate/Utility Type | |
| | | | | | N/A | | | N/A |
| | | | | | | Yes | Surface Condition? (G/P) | Good |
| | | | | | | | | |

Flare Traversable LT?