

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10031810	Main Str	Main Street: MILLENNIUM_AV			Cross Street: SAGE_PARK_DR				w	
ADA ID: F6F2F9AEE942	Ramp Ty	Ramp Type: Directional1			ail: Fail Overall	o Severity Score:	1.25			
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	11 18	Possible Solutions:		Compliance Description			Data Compliance Description			
18/2012	H. C.S.L.	Remove & Replace Entire Ram	Э.	N/A	Ramp Length (in)	68.0	N/A	Grade Break?	N/A	
				Yes	Ramp Width (in)	69.0	N/A	Grade Break Slope (%)	0.0	
	0 DA			Yes	Ramp Slope (%)	3.6	N/A	Grade Break XSlope (%)	0.0	
De la serie de la	ISAN I			No	Ramp XSlope (%)	2.2				
All and a set of the s	ALLA			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	HAN N			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
the the the test of te		Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
		N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
the the	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
				N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
6	the second			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
the second se		PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
the second		R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
	6 de la			N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
206 21				N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
A A A A A A A A A A A A A A A A A A A				N/A	Painted X Walk1?	No		Road Slope (%)	0.1	
Street 1 Name	SAGE PARK DR				X Walk 1 Direction	To SE		Road X Slope (%)	2.7	
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A	
Street 2 Name	N/A				X Walk 1 Slope (%)	0.1	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	2.7	N/A	Storm Grate/Utility Hazard?	N/A	
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
				N/A	Any Obstructions?	N/A			N/A	
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
						N/A	N/A	Curb Slope (%)	5.5	

