


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

| | | | |
|---------------------------|---------------------------|-------------------------|------------------------|
| Intersection ID: 10022718 | Main Street: CAROWINDS_BV | Cross Street: N/A | Location: NW |
| ADA ID: F836C5147C94 | Ramp Type: PerpDiag | Initial Pass/Fail: Fail | Overall Compliance: No |
| | | | Severity Score: 21.25 |

| Codes/Mitigation Info/Possible Solution | | | Field Measurements/Component Compliance | | |
|--|---|------------|---|-----------------------------|-------------|
|  | Possible Solutions: | | Compliance | Description | Data |
| | Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. | | No | Ramp Length (in) | 50.0 |
| | | | No | Ramp Width (in) | 37.5 |
| | | | N/A | Flare Type LT | N/A |
| | | | N/A | Flare Slope LT (%) | N/A |
| | | | N/A | Flare Traversable LT? | N/A |
| | | | N/A | Landing Length (in) | N/A |
| | | | N/A | Landing Width (in) | N/A |
| | | | N/A | Landing Slope (%) | N/A |
| | | | N/A | Landing X Slope (%) | N/A |
| | | | N/A | Landing Curb? (Y/N) | N/A |
| | | | N/A | Shared Landing? | N/A |
| | | | N/A | Gutter Ponding? | N/A |
| | | | N/A | Gutter Lip Ht (in) | N/A |
| | | | N/A | Painted X Walk1? | No |
| | | | N/A | X Walk 1 Direction | To S |
| | | | N/A | X Walk 1 Width (in) | N/A |
| | | | N/A | X Walk 1 Slope (%) | 2.4 |
| | | | N/A | X Walk 1 X Slope (%) | 1.4 |
| | | | N/A | Ramp inside XWalk1? | N/A |
| <p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>R304.5.1, R304.2.2</p> | | | N/A | Flare Type RT | N/A |
| | | | N/A | Flare Slope RT (%) | N/A |
| | | | N/A | Flare Traversable RT? | N/A |
| | | | N/A | DWS Provided? | N/A |
| | | | N/A | DWS Contrast? | N/A |
| | | | N/A | DWS Length (in) | N/A |
| | | | N/A | DWS Full Width? | N/A |
| | | | N/A | DWS Offset (in) | N/A |
| | | | N/A | Gutter Slope (%) | N/A |
| | | | N/A | Gutter X Slope (%) | N/A |
| | | | N/A | Painted X Walk2? | No |
| | | | N/A | X Walk 2 Direction | To E |
| | | | N/A | X Walk 2 Width (in) | N/A |
| | | | N/A | X Walk 2 Slope (%) | 1.9 |
| | | | N/A | X Walk 2 X Slope (%) | 0.5 |
| | | | N/A | Ramp inside XWalk2? | N/A |
| | | | N/A | Clear Space? | N/A |
| | | | N/A | Clear Space to XWalk (in) | N/A |
| | | | N/A | Storm Grate/Utility Hazard? | N/A |
| | | | N/A | Storm Grate/Utility Type | N/A |
| | | | N/A | Surface Condition? (G/P) | Good |
| Total Cost: | | \$ 3200.00 | | | |

| | |
|-------------------------|---------------|
| Street 1 Name | ENTRANCE |
| Stop Condition-Street 2 | StopSign |
| Street 2 Name | CARROWINDS BV |
| Stop Condition-Street 1 | None |

