## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



tersection ID: 10034226 Main Street: PEBBLE_RUN_DR		Cross Str	eet:	N/A	Location:	NE			
ADA ID: F96551F0BE90 Ramp T	96551F0BE90 Ramp Type: BlendTrans1		s/Fa	il: Fail Overall (	o Severity Score:	10			
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
	Possible Solutions:	c	Compliance Description			Data Compliance Description			
	Remove & Replace Curb Ramp W Two New Directional Ramps or Equivalent.	Nith N	/A	Ramp Length (in)	49.5	Yes	BlendTrans Slope (%)	4.2	
		N	0	Ramp Width (in)	47.5	No	BlendTrans XSlope (%)	2.2	
		N	/ <b>A</b>	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	-	N	/ <b>A</b>	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
		N	/ <b>A</b>	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
		N	/ <b>A</b>	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	Surveyor Notes:	N	/ <b>A</b>	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	N/A	N	/ <b>A</b>	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
		N	/ <b>A</b>	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
		N	/ <b>A</b>	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
		N	/ <b>A</b>	Shared Landing?	N/A				
Charles AN	PROW/ADA:	N	/ <b>A</b>	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	Not Found, R304.5.1, R304.5.3	N	A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
A CARLER AND A CARLE			/ <b>A</b>	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
				X Walk 1 Direction	To NW		X Walk 2 Direction	N/A	
				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
Street 1 Name PEBBLE RUN DR	-			X Walk 1 Slope (%)	1.9		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 1 None				X Walk 1 X Slope (%)	1.3		X Walk 2 X Slope (%)	N/A	
Street 2 Name N/A		N	/ <b>A</b>	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 2 N/A				Road Slope (%)	1.3		Clear Space?	N/A	
				Road X Slope (%)	1.9	N/A	Clear Space to XWalk (in)	N/A	
		N	/ <b>A</b>	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type		
					N/A			N/A	







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

10.6