cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



		-								
Intersection ID: 18797	Main Street: SENECA_PL			et: V	VEDGEWOOD_DR	Location:	SW			
ADA ID: FA32075573D7	Ramp Type: BlendTrans1			s/Fail	: Fail Overall C	o Severity Score:	12.5			
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:	Co					ompliance Description		
		Remove & Replace Curb Ramp W			Ramp Length (in)	83.0	Yes	BlendTrans Slope (%)	2.7	
		Two New Directional Ramps or	Ye		Ramp Width (in)	72.0	No	BlendTrans XSlope (%)	6.5	
		Equivalent.	N//		Flare Type LT	N/A	N/A	Flare Type RT	N/A	
			N//		Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
			N//		Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
THEOR PL H			N//		Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
		Surveyor Notes:	N/A		Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
		N/A	N//		Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
the second second		1/4	N//		Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
A CARLER OF CARLES	1		N//		Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
		A	N//		Shared Landing?	N/A				
		PROW/ADA:	N//		Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
A second and a second as a		Not Found, R304.5.3	N//		Gutter Lip Ht (in)	N/A		Gutter X Slope (%)	N/A	
and the second s	A Start A	Not i Cuna, Roo4.0.0	N//		Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
					X Walk 1 Direction	To N		X Walk 2 Direction	N/A	
				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A		
Street 1 Name	SENECA PL				X Walk 1 Slope (%)	6.5		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 1	None				X Walk 1 X Slope (%)	5.6		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A		N//		Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 2	N/A				Road Slope (%)	5.6		Clear Space?	N/A	
					Road X Slope (%)	6.5	N/A	Clear Space to XWalk (in)	N/A	
			N//		Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$ 32	00.00		Obstruction Type			Storm Grate/Utility Type		
		•	-		<i>,</i> ,	N/A			N/A	





Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

6.2