

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: 15139 Main Street: EAST BV **Cross Street: KENILWORTH AV** Location: **Overall Compliance: No ADA ID: FAC3681D3D88** Ramp Type: PerpDiag Initial Pass/Fail: Fail Severity Score: 26.25

**Codes/Mitigation Info/Possible Solution** 

Field Measurements/Component Compliance



**EAST BV** Street 1 Name Stop Condition-Street 2 Signal **KENILWORTH AV** Street 2 Name Stop Condition-Street 1 Signal

**Remove & Replace Curb Ramp With Two New Directional Ramps or** Equivalent. Surveyor Notes:

PROW/ADA:

N/A

R304.2.2, R304.5.3





Total Cost:



3200.00

| Compliance Description |                       | Data  | Comp | oliance Description         | Data  |
|------------------------|-----------------------|-------|------|-----------------------------|-------|
| N/A                    | Ramp Length (in)      | 49.0  | No   | Ramp Slope (%)              | 13.7  |
| Yes                    | Ramp Width (in)       | 48.0  | No   | Ramp XSlope (%)             | 3.5   |
| N/A                    | Flare Type LT         | N/A   | N/A  | Flare Type RT               | N/A   |
| N/A                    | Flare Slope LT (%)    | N/A   | N/A  | Flare Slope RT (%)          | N/A   |
| N/A                    | Flare Traversable LT? | N/A   | N/A  | Flare Traversable RT?       | N/A   |
| N/A                    | Landing Length (in)   | N/A   | N/A  | DWS Provided?               | N/A   |
| N/A                    | Landing Width (in)    | N/A   | N/A  | DWS Contrast?               | N/A   |
| N/A                    | Landing Slope (%)     | N/A   | N/A  | DWS Length (in)             | N/A   |
| N/A                    | Landing X Slope (%)   | N/A   | N/A  | DWS Full Width?             | N/A   |
| N/A                    | Landing Curb? (Y/N)   | N/A   | N/A  | DWS Offset (in)             | N/A   |
| N/A                    | Shared Landing?       | N/A   |      |                             |       |
| N/A                    | Gutter Ponding?       | N/A   | N/A  | Gutter Slope (%)            | N/A   |
| N/A                    | Gutter Lip Ht (in)    | N/A   | N/A  | Gutter X Slope (%)          | N/A   |
| N/A                    | Painted X Walk1?      | Yes   | N/A  | Painted X Walk2?            | Yes   |
|                        | X Walk 1 Direction    | To SW |      | X Walk 2 Direction          | To SE |
| N/A                    | X Walk 1 Width (in)   | 110.0 | N/A  | X Walk 2 Width (in)         | 110.0 |
|                        | X Walk 1 Slope (%)    | 6.1   |      | X Walk 2 Slope (%)          | 1.4   |
|                        | X Walk 1 X Slope (%)  | 0.7   |      | X Walk 2 X Slope (%)        | 1.6   |
| N/A                    | Ramp inside XWalk1?   | Yes   | N/A  | Ramp inside XWalk2?         | Yes   |
|                        | Road Slope (%)        | 2.7   | N/A  | Clear Space?                | N/A   |
|                        | Road X Slope (%)      | 1.4   | N/A  | Clear Space to XWalk (in)   | N/A   |
| N/A                    | Any Obstructions?     | N/A   | N/A  | Storm Grate/Utility Hazard? | N/A   |
|                        | Obstruction Type      |       |      | Storm Grate/Utility Type    |       |
|                        |                       | N/A   |      |                             | N/A   |
|                        |                       |       | Yes  | Surface Condition? (G/P)    | Good  |