

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Curb Slope (%)

4.1

Intersection ID: 8445	Main Street: IRMA_ST		Cross Street: LASALLE_ST			Location:	NW
ADA ID: FDCDCCD6E74B	Ramp Type: Combination1Diag	Initial	Pass/Fa	ail: Fail Overall C	omplianc	e: No Severity Score:	0
Codes/		Field Measurements/Component Compliance					
	Possible Solutions:		Compl	liance Description	Data	Compliance Description	Data
	Remove & Replace Curb Ran	no With	N/A	Ramp Length LT (in)	41.0	N/A Ramp Length RT (in)	53.0
	Two New Directional Ramps		Yes	Ramp Width LT (in)	74.0	Yes Ramp Width RT (in)	74.0
	Equivalent.		No	Ramp Slope LT (%)	12.1	Yes Ramp Slope RT (%)	4.7
			No	Ramp XSlope LT (%)	2.8	Yes Ramp XSlope RT (%)	2.0
S have the state			N/A	Ramp Length (in)	72.0	Yes Ramp Slope (%)	3.2
			No	Ramp Width (in)	47.0	No Ramp XSlope (%)	7.9
	Surveyor Notes:		N/A	Flare Type LT	N/A	N/A Flare Type RT	N/A
the second secon	RP & RT RP < 5%		N/A	Flare Slope LT (%)	N/A	N/A Flare Slope RT (%)	N/A
LADALLE ST	and the second s		N/A	Flare Traversable LT?	N/A	N/A Flare Traversable RT?	N/A
E CARACTER T			N/A	Landing Length (in)	N/A	N/A DWS Provided?	N/A
	A DECEMBER OF A		N/A	Landing Width (in)	N/A	N/A DWS Contrast?	N/A
the I I	PROW/ADA:		N/A	Landing Slope (%)	N/A	N/A DWS Length (in)	N/A
	R304.5.1, R304.5.3, R304.3.2		N/A	Landing X Slope (%)	N/A	N/A DWS Full Width?	N/A
			N/A	Landing Curb? (Y/N)	N/A	N/A DWS Offset (in)	N/A
			N/A	Shared Landing?	N/A		
	TOT-		N/A	Gutter Ponding?	N/A	N/A Gutter Slope (%)	N/A
Street 1 Name	None		N/A	Gutter Lip Ht (in)	N/A	N/A Gutter X Slope (%)	N/A
Stop Condition-Street 1	LASALLE ST		N/A	Painted X Walk1?	No	N/A Painted X Walk2?	No
Street 2 Name	StopSign			X Walk 1 Direction	To S	X Walk 2 Direction	To E
Stop Condition-Street 2	IRMA ST			X Walk 1 Width (in)	N/A	X Walk 2 Width (in)	N/A
				X Walk 1 Slope (%)	6.8	X Walk 2 Slope (%)	0.7
				X Walk 1 X Slope (%)	6.1	X Walk 2 X Slope (%)	9.9
	Total Cost: \$	3200.00	N/A	Ramp inside XWalk1?	N/A	N/A Ramp inside XWalk2?	N/A
				Road Slope (%)	6.1	Clear Space?	N/A
				Road X Slope (%)	1.9	N/A Clear Space to XWalk (in)	N/A
						N/A Any Obstruction?	N/A
						Obstruction Type	
All and a second second			and the second				N/A
				The state of the		N/A Storm Grate/Utility Hazard?	N/A
				the second		Storm Grate/Utility Type	N/A
		1					N/A
						Yes Surface Condition? (G/P)	Good