

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data 5.8 1.9 N/A N/A N/A N/A N/A N/A N/A N/A

> N/A N/A N/A N/A N/A N/A N/A N/A N/A N/A

N/A

N/A

Good

Surface Condition? (G/P)

Intersection ID: N/A Main Street: ELGIN_MOOR_RD **Cross Street: LANGWELL_LN** Location: SE ADA ID: FE066DC71A9F Ramp Type: Perp Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 8.75

Codes/Mitigation Info/Possible Solution



Street 1 Name	ELGIN MOOR RD
Stop Condition-Street 2	None
Street 2 Name	N/A
Stop Condition-Street 1	N/A

/Possible Solution			Field Measurements/Component Compliance						
Possible Solutions:			Comp	Data	Comp	liance	Description		
Remove & Replace Entire	Ram	ıp.	N/A	Ramp Length (in)	48.0	Yes	Ramp	Slope (%)	
			No	Ramp Width (in)	46.5	Yes	Ramp	XSlope (%)	
			N/A	Flare Type LT	N/A	N/A	Flare	Type RT	
			N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	
4			N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	
			N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	
Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	
N/A			N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	
7			N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	
			N/A	Shared Landing?	N/A				
PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutte	Slope (%)	
Not Found, R304.5.1			N/A	Gutter Lip Ht (in)	1.0	N/A	Gutte	X Slope (%)	
			N/A	Painted X Walk1?	No	N/A	Painte	ed X Walk2?	
				X Walk 1 Direction	To NW		X Wal	k 2 Direction	
			N/A	X Walk 1 Width (in)	N/A	N/A	X Wal	k 2 Width (in)	
				X Walk 1 Slope (%)	2.4		X Wal	k 2 Slope (%)	
				X Walk 1 X Slope (%)	4.2		X Wal	k 2 X Slope (%)	
			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp	inside XWalk2?	
				Road Slope (%)	N/A	N/A	Clear	Space?	
				Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	
			N/A	Any Obstructions?	N/A	N/A	Storm	Grate/Utility Hazard?	
Total Cost:	\$	1850.00		Obstruction Type			Storm	Grate/Utility Type	





