

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 12909	12909 Main Street: FULTON_AV			Cross Street: RANDALL_ST					SW	
ADA ID: FE74A55B77CF	A ID: FE74A55B77CF Ramp Type: Perp			ass/Fa	ail: Fail Overall C	Severity Score:	18.75			
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	5	Possible Solutions:		Compliance Description D			Data Compliance Description		Data	
		Remove & Replace Entire Ramp	-	N/A	Ramp Length (in)	46.0	Yes	Ramp Slope (%)	8.3	
	Minaria Minara Bar			No	Ramp Width (in)	35.0	No	Ramp XSlope (%)	3.3	
	The second			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	and the state			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
	The Lateria			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
the second se				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
RANDALLOU	the set of the	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
	****(1)公元:*			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
	A Color of Color			N/A	Shared Landing?	N/A				
ALL AND A REAL PROPERTY AN	State -	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	(3)	Not Found, R304.5.1, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
And the second second second				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
					X Walk 1 Direction	To N		X Walk 2 Direction	N/A	
The second	Contraction of			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	RANDALL ST				X Walk 1 Slope (%)	6.8		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	3.4		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A	
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	

Yes Surface Condition? (G/P)

Good

