cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 13741	Main Street: CRICKLEWOOD_LN			Street:	VERNEDALE_RD	Location:	SE		
ADA ID: FED03995C93F	Ramp Type: BlendTrans1			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	8.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	South and a	Possible Solutions:		Compliance Description			Data Compliance Description		Data
	L Free	Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	87.5	Yes	BlendTrans Slope (%)	3.8
		Two New Directional Ramps or		No	Ramp Width (in)	47.5	Yes	BlendTrans XSlope (%)	0.4
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
E ORICKLEY	VOOD ER			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
la la	COL Pro	9		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
the second se	11.00			N/A	Shared Landing?	N/A			
1 12 30 14		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	NE Cardel	Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
A. F. O. A.	(D) and (,		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
2				X Walk 1 Direction	To NW		X Walk 2 Direction	N/A	
al of a				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
Street 1 Name CRI	CKLEWOOD LN	_			X Walk 1 Slope (%)	1.9		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	StopSign				X Walk 1 X Slope (%)	0.9		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A				Road Slope (%)	0.9		Clear Space?	N/A
					Road X Slope (%)	1.9	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

14.6