

A photograph showing a concrete sidewalk with a black metal pole on the right. In the background, there is a white building with a white staircase and some trees. The image is used to illustrate the 'Normal' condition of the sidewalk.

MUTCD Compliance					
Yes	B 1 Clear Xing Direction?	ClearlyMarked	N/A	B 2 Clear Xing Direction?	N/A
	B 1 Crossing Direction	To SE		B 2 Crossing Direction	N/A
Yes	B 1 DistanceTo XWalk (in)	34.0	N/A	B 2 DistanceTo XWalk (in)	N/A
Yes	B 1 DistanceTo Curb (in)	51.0	N/A	B 2 DistanceTo Curb (in)	N/A
Yes	B 1 Diameter (in)	2.0	N/A	B 2 Diameter (in)	N/A