

Access Compliance Report

Public Rights-of-Way

(Island Curb Cuts)

Intersection ID: 10868	Main Street: N_TRYON_ST	Cross Street: DALTON_AV	Location: SW
ADA ID: 0773AAA0C2C1	Curb Cut Type: IslandRefuge3	Initial Pass/Fail: Pass	Overall Compliance: No
Severity Score: 17.5			
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	



Possible Solutions:

**Remove & Replace Entire Refuge.
Grind Gutter Lip.**

Surveyor Notes:

N/A

PROW/ADA:

N/A

Total Cost: \$ 3400.00



Compliance	Description	Data	Compliance	Description	Data
No	Refuge 1 Length (In)	34.5	Yes	Gutter 1 Ponding?	No
Yes	Refuge 1 Width (In)	85.0	No	Gutter 1 Lip Ht (In)	0.5
Yes	Refuge 1 Slope (%)	0.2	Yes	Gutter 1 Slope (%)	0.6
Yes	Refuge 1 X Slope (%)	0.3	Yes	Gutter 1 X Slope (%)	0.0
N/A	Painted X Walk1?	Yes	No	DWS 1 Provided?	Yes
N/A	X Walk 1 Direction	To SW	N/A	DWS 1 Contrast?	Yes
N/A	X Walk 1 Width (In)	113.5	N/A	DWS 1 Length (In)	24.0
N/A	Road 1 Slope (%)	0.8	N/A	DWS 1 Full Width?	No
N/A	Road 1 X Slope (%)	0.3	N/A	DWS 1 Offset (In)	20.5
No	Refuge 2 Length (In)	30.0	Yes	Gutter 2 Ponding?	No
Yes	Refuge 2 Width (In)	85.0	No	Gutter 2 Lip Ht (In)	0.5
Yes	Refuge 2 Slope (%)	0.8	Yes	Gutter 2 Slope (%)	1.3
Yes	Refuge 2 X Slope (%)	1.8	Yes	Gutter 2 X Slope (%)	1.2
N/A	Painted X Walk2?	Yes	No	DWS 2 Provided?	Yes
N/A	X Walk 2 Direction	To NE	N/A	DWS 2 Contrast?	Yes
N/A	X Walk 2 Width (In)	112.0	N/A	DWS 2 Length (In)	24.0
N/A	Road 2 Slope (%)	1.2	N/A	DWS 2 Full Width?	No
N/A	Road 2 X Slope (%)	0.5	N/A	DWS 2 Offset (In)	2.5
No	Refuge 3 Length (in)	73.0	Yes	Gutter 3 Ponding?	No
Yes	Refuge 3 Width (in)	73.5	Yes	Gutter 3 Lip Ht (in)	0.0
Yes	Refuge 3 Slope (%)	1.7	Yes	Gutter 3 Slope (%)	1.9
Yes	Refuge 3 XSlope (%)	0.3	Yes	Gutter 3 XSlope (%)	1.6
N/A	Painted X Walk3?	Yes	No	DWS 3 Provided?	Yes
N/A	X Walk 3 Direction	To SE	N/A	DWS 3 Contrast?	Yes
N/A	X Walk 3 Width (in)	107.0	N/A	DWS 3 Length (in)	24.0
N/A	Road 3 Slope (%)	1.1	N/A	DWS 3 Full Width?	No
N/A	Road 3 XSlope (%)	1.2	N/A	DWS 3 Offset (in)	2.5
Yes	Any Obstructions?	No	N/A	Storm Grate/Utility Hazard?	No
N/A	Obstruction Type	N/A	N/A	Storm Grate/Utility Type	N/A
N/A	Surface Condition	Good			