

Access Compliance Report

Public Rights-of-Way

(Island Curb Cuts)

Intersection ID: 11331	Main Street: E_W_T_HARRIS_BV	Cross Street: MEADOW_ROSE_LN	Location: NW
ADA ID: 0FDB6EEC54E8	Curb Cut Type: IslandRefuge3	Initial Pass/Fail: Pass	Overall Compliance: No
Severity Score: 12.5			
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	



Possible Solutions:

Grind Gutter Lip.

Surveyor Notes:

N/A

PROW/ADA:

N/A

Total Cost: \$ 600.00



Compliance	Description	Data	Compliance	Description	Data
Yes	Refuge 1 Length (In)	356.0	No	Gutter 1 Ponding?	Yes
Yes	Refuge 1 Width (In)	96.5	No	Gutter 1 Lip Ht (In)	0.25
Yes	Refuge 1 Slope (%)	1.6	Yes	Gutter 1 Slope (%)	1.0
Yes	Refuge 1 X Slope (%)	1.6	Yes	Gutter 1 X Slope (%)	2.6
N/A	Painted X Walk1?	Yes	Yes	DWS 1 Provided?	Yes
N/A	X Walk 1 Direction	To NW	Yes	DWS 1 Contrast?	Yes
N/A	X Walk 1 Width (In)	111.5	Yes	DWS 1 Length (In)	24.0
N/A	Road 1 Slope (%)	1.7	Yes	DWS 1 Full Width?	Yes
N/A	Road 1 X Slope (%)	0.7	Yes	DWS 1 Offset (In)	2.0
Yes	Refuge 2 Length (In)	42.5	No	Gutter 2 Ponding?	Yes
Yes	Refuge 2 Width (In)	118.0	No	Gutter 2 Lip Ht (In)	0.5
Yes	Refuge 2 Slope (%)	0.8	Yes	Gutter 2 Slope (%)	0.4
Yes	Refuge 2 X Slope (%)	0.8	Yes	Gutter 2 X Slope (%)	1.8
N/A	Painted X Walk2?	Yes	Yes	DWS 2 Provided?	Yes
N/A	X Walk 2 Direction	To NE	Yes	DWS 2 Contrast?	Yes
N/A	X Walk 2 Width (In)	128.5	Yes	DWS 2 Length (In)	24.0
N/A	Road 2 Slope (%)	1.6	Yes	DWS 2 Full Width?	Yes
N/A	Road 2 X Slope (%)	3.2	Yes	DWS 2 Offset (In)	0.0
Yes	Refuge 3 Length (in)	41.0	No	Gutter 3 Ponding?	Yes
Yes	Refuge 3 Width (in)	120.0	No	Gutter 3 Lip Ht (in)	0.25
Yes	Refuge 3 Slope (%)	2.0	Yes	Gutter 3 Slope (%)	2.5
Yes	Refuge 3 XSlope (%)	0.1	Yes	Gutter 3 XSlope (%)	0.5
N/A	Painted X Walk3?	Yes	Yes	DWS 3 Provided?	Yes
N/A	X Walk 3 Direction	To SE	Yes	DWS 3 Contrast?	Yes
N/A	X Walk 3 Width (in)	116.0	Yes	DWS 3 Length (in)	24.0
N/A	Road 3 Slope (%)	0.4	Yes	DWS 3 Full Width?	Yes
N/A	Road 3 XSlope (%)	0.9	Yes	DWS 3 Offset (in)	0.0
Yes	Any Obstructions?	No	N/A	Storm Grate/Utility Hazard?	No
N/A	Obstruction Type	N/A	N/A	Storm Grate/Utility Type	N/A
N/A	Surface Condition	Good			