cole

Access Compliance Report Public Rights-of-Way (Island Curb Cuts)



Intersection ID: 10038264 Main Street: SMITH_RD				eet: N/A		Location:	S	
					erall Compliance			
ADA ID: 1E226F73B7DB Curb Cut Type: MedianRefuge2			1 1 4 5 5				0	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance				
	Possible Solutions:		Com	pliance Description	Data Con		Data	
	Remove & Replace Entire Refuge		Yes	Refuge 1 Length (In)	52.5 N/A	Gutter 1 Ponding?	N/A	
			Yes	Refuge 1 Width (In)	99.0 N/A	Gutter 1 Lip Ht (In)	N/A	
			Yes	Refuge 1 Slope (%)	1.6 N/A	,	N/A	
			Yes	Refuge 1 X Slope (%)	3.5 N/A	,	N/A	
			N/A	Painted X Walk1?	No N/A	DWS 1 Provided?	N/A	
			N/A	X Walk 1 Direction	To SE N/A		N/A	
No contraction of the second sec	Surveyor Notes:			X Walk 1 Width (In)	N/A N/A	ö ()	N/A	
6	N/A		N/A	Road 1 Slope (%)	3.3 N/A		N/A	
			N/A	Road 1 X Slope (%)	1.6 N/A	DWS 1 Offset (In)	N/A	
	7		Yes	Refuge 2 Length (In)	52.5 N/A	Gutter 2 Ponding?	N/A	
			Yes	Refuge 2 Width (In)	99.0 N/A	Gutter 2 Lip Ht (In)	N/A	
	Contract 1		Yes	Refuge 2 Slope (%)	1.2 N/A	Gutter 2 Slope (%)	N/A	
	PROW/ADA:		Yes	Refuge 2 X Slope (%)	4.8 N/A	Gutter 2 X Slope (%)	N/A	
	N/A		N/A	Painted X Walk2?	No N/A	DWS 2 Provided?	N/A	
			N/A	X Walk 2 Direction	To NW N/A	DWS 2 Contrast?	N/A	
			N/A	X Walk 2 Width (In)	N/A N/A	DWS 2 Length (In)	N/A	
			N/A	Road 2 Slope (%)	3.3 N/A	DWS 2 Full Width?	N/A	
			N/A	Road 2 X Slope (%)	7.3 N/A	DWS 2 Offset (In)	N/A	
			N/A	Refuge 3 Length (in)	N/A N/A	Gutter 3 Ponding?	N/A	
	Total Cost: \$ 30	00.00	N/A	Refuge 3 Width (in)	N/A N/A	-	N/A	
			N/A	Refuge 3 Slope (%)	N/A N/A		N/A	
			N/A	Refuge 3 XSlope (%)	N/A N/A		N/A	
			N/A	Painted X Walk3?	N/A N/A	DWS 3 Provided?	N/A	
			N/A	X Walk 3 Direction	N/A N/A	DWS 3 Contrast?	N/A	
			N/A	X Walk 3 Width (in)	N/A N/A	DWS 3 Length (in)	N/A	
			N/A	Road 3 Slope (%)	N/A N/A	DWS 3 Full Width?	N/A	
				Road 3 XSlope (%)	N/A N/A	DWS 3 Offset (in)	N/A	
		Chilles .	Yes	Any Obstructions?	N/A N/A	Storm Grate/Utility Hazard?	N/A	
			N/A	Obstruction Type	N/A	Storm Grate/Utility Type		
					N/A		N/A	
			N/A	Surface Condition	Good			