## cole

## Access Compliance Report Public Rights-of-Way (Island Curb Cuts)



Intersection ID: 10025393 Main Street: E_ARROWOOD_RD 0				et: N/A			Location:	Е
ADA ID: 1FE0050BF6C8 Curb Cut Type: MedianRefuge2			nitial Pass/Fail: Fail Overall Compliance			ince		
								. 12.0
Codes/Mitigation Info/Possible Solution							ponent Compliance	
	Possible Solutions:			pliance Descrip			pliance Description	Data
Fast MA & CA	Remove & Replace Entire Refug	e.		Refuge 1 Length (In	,		Gutter 1 Ponding?	N/A
	and the second s		Yes	Refuge 1 Width (In)			Gutter 1 Lip Ht (In)	N/A
and the state with the second second			Yes	Refuge 1 Slope (%)		N/A	,	N/A
			No	Refuge 1 X Slope (%		N/A	,	N/A
			N/A	Painted X Walk1?		N/A		N/A
h			N/A	X Walk 1 Direction	To N		DWS 1 Contrast?	N/A
THE DOCTOR	Surveyor Notes:		N/A	X Walk 1 Width (In)		N/A	DWS 1 Length (In)	N/A
EARROUNCE	N/A		N/A	Road 1 Slope (%)			DWS 1 Full Width?	N/A
6			N/A	Road 1 X Slope (%)	) 2.2	N/A	DWS 1 Offset (In)	N/A
CANT ON ANT			Yes	Refuge 2 Length (In	37 5	NI/A	Gutter 2 Ponding?	N/A
			Yes	Refuge 2 Width (In)			Gutter 2 Lip Ht (In)	N/A N/A
				,				N/A N/A
The seal of the se	PROW/ADA:		Yes No	Refuge 2 Slope (%) Refuge 2 X Slope (%		N/A	Gutter 2 X Slope (%)	N/A N/A
	120		N/A	Painted X Walk2?			DWS 2 Provided?	N/A
all a set all	N/A		N/A	X Walk 2 Direction			DWS 2 Contrast?	N/A N/A
				X Walk 2 Width (In)				N/A N/A
			N/A N/A	Road 2 Slope (%)			DWS 2 Length (In) DWS 2 Full Width?	N/A N/A
			N/A	Road 2 X Slope (%)			DWS 2 Offset (In)	
			N/A	Road 2 A Slope (%)	, 1.7	N/A	DWS 2 Oliset (III)	N/A
			N/A	Refuge 3 Length (in	) <b>N/A</b>	N/A	Gutter 3 Ponding?	N/A
	Total Cost: \$	3000.00	N/A	Refuge 3 Width (in)	N/A	N/A	Gutter 3 Lip Ht (in)	N/A
			N/A	Refuge 3 Slope (%)	N/A	N/A	Gutter 3 Slope (%)	N/A
			N/A	Refuge 3 XSlope (%	%) N/A	N/A	Gutter 3 XSlope (%)	N/A
			N/A	Painted X Walk3?	N/A	N/A	DWS 3 Provided?	N/A
			N/A	X Walk 3 Direction	N/A	N/A	DWS 3 Contrast?	N/A
			N/A	X Walk 3 Width (in)	N/A	N/A	DWS 3 Length (in)	N/A
			N/A	Road 3 Slope (%)	N/A	N/A	DWS 3 Full Width?	N/A
			N/A	Road 3 XSlope (%)	N/A	N/A	DWS 3 Offset (in)	N/A
			Yes	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
			N/A	Obstruction Type		N/A	Storm Grate/Utility Type	
					N/A			N/A
		The	N/A	Surface Condition	Good	I		