

## Access Compliance Report Public Rights-of-Way (Island Curb Cuts)



Data

N/A

N/A

N/A

N/A

N/A

Intersection ID: 9068Main Street: W\_TRADE\_STCross Street: ROZZELLES\_FERRY\_RDLocation:NADA ID: 524D7476E32DCurb Cut Type: IslandRefuge3Initial Pass/Fail: FailOverall Compliance: NoSeverity Score:60

Compliance

Yes

Description

Refuge 1 Length (In)

Refuge 1 Width (In)

Refuge 1 Slope (%)

Painted X Walk1?

Refuge 1 X Slope (%)

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance

Data Compliance Description

119.0 N/A Gutter 1 Ponding?

**58.5 N/A** Gutter 1 Lip Ht (In)

**4.3** N/A Gutter 1 Slope (%)

Yes N/A DWS 1 Provided?

**5.1 N/A** Gutter 1 X Slope (%)



Possible Solutions:

Remove & Replace Entire Refuge.

Surveyor Notes:

N/A

Total Cost: \$ 3000.00



11/7	I allited A Walk I:	100 1107	DVVO 11 lovided:	11/7
N/A	X Walk 1 Direction	To S N/A	DWS 1 Contrast?	N/A
N/A	X Walk 1 Width (In)	108.0 N/A	DWS 1 Length (In)	N/A
N/A	Road 1 Slope (%)	4.3 N/A	DWS 1 Full Width?	N/A
N/A	Road 1 X Slope (%)	5.0 N/A	DWS 1 Offset (In)	N/A
Yes	Refuge 2 Length (In)	147.0 N/A	Gutter 2 Ponding?	N/A
No	Refuge 2 Width (In)	58.0 N/A	Gutter 2 Lip Ht (In)	N/A
No	Refuge 2 Slope (%)	6.0 N/A	Gutter 2 Slope (%)	N/A
No	Refuge 2 X Slope (%)	5.8 N/A	Gutter 2 X Slope (%)	N/A
N/A	Painted X Walk2?	Yes N/A	DWS 2 Provided?	N/A
N/A	X Walk 2 Direction	To E N/A	DWS 2 Contrast?	N/A
N/A	X Walk 2 Width (In)	111.0 N/A	DWS 2 Length (In)	N/A
N/A	Road 2 Slope (%)	4.4 N/A	DWS 2 Full Width?	N/A
N/A	Road 2 X Slope (%)	3.3 N/A	DWS 2 Offset (In)	N/A
Yes	Refuge 3 Length (in)	180.0 N/A	Gutter 3 Ponding?	N/A
No	Refuge 3 Width (in)	59.0 N/A	Gutter 3 Lip Ht (in)	N/A
Yes	Refuge 3 Slope (%)	2.6 N/A	Gutter 3 Slope (%)	N/A
No	Refuge 3 XSlope (%)	7.4 N/A	Gutter 3 XSlope (%)	N/A
N/A	Painted X Walk3?	Yes N/A	DWS 3 Provided?	N/A
N/A	X Walk 3 Direction	To N N/A	DWS 3 Contrast?	N/A
N/A	X Walk 3 Width (in)	110.0 N/A	DWS 3 Length (in)	N/A
N/A	Road 3 Slope (%)	7.3 N/A	DWS 3 Full Width?	N/A
N/A	Road 3 XSlope (%)	1.4 N/A	DWS 3 Offset (in)	N/A
Yes	Any Obstructions?	N/A N/A	Storm Grate/Utility Hazard?	N/A
N/A	Obstruction Type	N/A	Storm Grate/Utility Type	
		N/A		N/A
N/A	Surface Condition	Good		





