

Access Compliance Report Public Rights-of-Way (Island Curb Cuts)



Data

No

0.5

5.9 1.9 Yes Yes

24.0

No 6.0

0.5 2.8

1.0

Yes Yes 24.0 No 7.0

N/A

Intersection ID: 11695 Main Street: PARKWOOD_AV Cross Street: THE_PLAZA Location: W

ADA ID: 524E89AC676B Curb Cut Type: MedianRefuge2 Initial Pass/Fail: Pass Overall Compliance: No Severity Score: 22.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Remove & Replace Detectable Warning System. Grind Gutter Lip. Remove & Replace Gutter.

Surveyor Notes:

Possible Solutions:

N/A

PROW/ADA:

N/A

Com	pliance	Description	Data	Com	pliance	Descrip
Yes	Refuge	1 Length (In)	72.0	Yes	Gutter 1	Ponding?
Yes	Refuge	1 Width (In)	94.0	No	Gutter 1	Lip Ht (In)
Yes	Refuge	1 Slope (%)	3.3	No	Gutter 1	Slope (%)
Yes	Refuge	1 X Slope (%)	0.4	Yes	Gutter 1	X Slope (
N/A	Painted	X Walk1?	Yes	Yes	DWS 1	Provided?
N/A	X Walk	1 Direction	To S	Yes	DWS 1	Contrast?
N/A	X Walk	1 Width (In)	110.5	Yes	DWS 1	Length (In)
N/A	Road 1	Slope (%)	1.0	No	DWS 1	Full Width?
N/A	Road 1	X Slope (%)	5.3	No	DWS 1	Offset (In)
Yes	Refuge	2 Length (In)	72.0	Yes	Gutter 2	Ponding?
Yes	Refuge	2 Width (In)	94.0	No	Gutter 2	Lip Ht (In)
Yes	Refuge	2 Slope (%)	0.7	Yes	Gutter 2	Slope (%)
Yes	Refuge	2 X Slope (%)	0.7	Yes	Gutter 2	X Slope (
N/A	Painted	X Walk2?	Yes	Yes	DWS 2	Provided?
N/A	X Walk	2 Direction	To N	Yes	DWS 2	Contrast?
N/A	X Walk	2 Width (In)	109.0	Yes	DWS 2	Length (In)
N/A	Road 2	Slope (%)	0.1	No	DWS 2	Full Width?
N/A	Road 2	X Slope (%)	5.0	No	DWS 2	Offset (In)
N/A	Refuge	3 Length (in)	N/A	N/A	Gutter 3	Ponding?



2550.00







N/A	Refuge 3 Width (in)	N/A N/A	Gutter 3 Lip Ht (in)	N/A
N/A	Refuge 3 Slope (%)	N/A N/A	Gutter 3 Slope (%)	N/A
N/A	Refuge 3 XSlope (%)	N/A N/A	Gutter 3 XSlope (%)	N/A
N/A	Painted X Walk3?	N/A N/A	DWS 3 Provided?	N/A
N/A	X Walk 3 Direction	N/A N/A	DWS 3 Contrast?	N/A
N/A	X Walk 3 Width (in)	N/A N/A	DWS 3 Length (in)	N/A
N/A	Road 3 Slope (%)	N/A N/A	DWS 3 Full Width?	N/A
N/A	Road 3 XSlope (%)	N/A N/A	DWS 3 Offset (in)	N/A
Yes	Any Obstructions?	No N/A	Storm Grate/Utility Hazard?	No
N/A	Obstruction Type	N/A	Storm Grate/Utility Type	
		N/A		N/A
N/A	Surface Condition	Good		