

Access Compliance Report Public Rights-of-Way (Island Curb Cuts)



Data

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Intersection ID: 18488Main Street: ABBEY_PLCross Street: PARK_RDLocation: WADA ID: 52A28028140FCurb Cut Type: MedianRefuge2Initial Pass/Fail: FailOverall Compliance: NoSeverity Score: 22.5

3000.00

Compliance

No

Yes

No

N/A

Description

Refuge 1 Length (In)

Refuge 1 Width (In)

Refuge 1 Slope (%)

Painted X Walk1?

X Walk 1 Direction

X Walk 1 Width (In)

Refuge 1 X Slope (%)

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Yes

To N N/A

190.0 N/A

Data Compliance

48.5 N/A Gutter 1 Ponding?

48.0 N/A Gutter 1 Lip Ht (In)

4.7 N/A Gutter 1 Slope (%)

6.6 N/A Gutter 1 X Slope (%)

DWS 1 Provided?

DWS 1 Contrast?

DWS 1 Length (In)

Description



Possible Solutions:

Remove & Replace Entire Refuge.

Surveyor Notes:

N/A

PROW/ADA:

Total Cost:

N/A







N/A	Road 1 Slope (%)	0.6	N/A	DWS 1 Full Width?	N/A
N/A	Road 1 X Slope (%)	0.2	N/A	DWS 1 Offset (In)	N/A
Yes	Refuge 2 Length (In)	48.5	N/A	Gutter 2 Ponding?	N/A
No	Refuge 2 Width (In)	48.0	N/A	Gutter 2 Lip Ht (In)	N/A
Yes	Refuge 2 Slope (%)	0.3	N/A	Gutter 2 Slope (%)	N/A
Yes	Refuge 2 X Slope (%)	4.4	N/A	Gutter 2 X Slope (%)	N/A
N/A	Painted X Walk2?	Yes	N/A	DWS 2 Provided?	N/A
N/A	X Walk 2 Direction	To S	N/A	DWS 2 Contrast?	N/A
N/A	X Walk 2 Width (In)	192.0	N/A	DWS 2 Length (In)	N/A
N/A	Road 2 Slope (%)	0.5	N/A	DWS 2 Full Width?	N/A
N/A	Road 2 X Slope (%)	1.3	N/A	DWS 2 Offset (In)	N/A
N/A	Refuge 3 Length (in)	N/A	N/A	Gutter 3 Ponding?	N/A
N/A	Refuge 3 Width (in)	N/A	N/A	Gutter 3 Lip Ht (in)	N/A
N/A	Refuge 3 Slope (%)	N/A	N/A	Gutter 3 Slope (%)	N/A
N/A	Refuge 3 XSlope (%)	N/A	N/A	Gutter 3 XSlope (%)	N/A
N/A	Painted X Walk3?	N/A	N/A	DWS 3 Provided?	N/A
N/A	X Walk 3 Direction	N/A	N/A	DWS 3 Contrast?	N/A
N/A	X Walk 3 Width (in)	N/A	N/A	DWS 3 Length (in)	N/A
N/A	Road 3 Slope (%)	N/A	N/A	DWS 3 Full Width?	N/A
N/A	Road 3 XSlope (%)	N/A	N/A	DWS 3 Offset (in)	N/A
Yes	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
N/A	Obstruction Type		N/A	Storm Grate/Utility Type	
		N/A			N/A
N/A	Surface Condition	Good			