

Access Compliance Report Public Rights-of-Way (Island Curb Cuts)



Data

N/A

N/A

N/A

N/A

N/A

Main Street: JIMMY OEHLER RD **Cross Street: N/A** Location: Ε Intersection ID: 53621 ADA ID: 543C85A85052 Curb Cut Type: MedianRefuge2 Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 0

Compliance

Description

Refuge 1 Length (In)

Refuge 1 Width (In)

Refuge 1 Slope (%)

Painted X Walk1?

Refuge 1 X Slope (%)

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Data Compliance Description

36.0 N/A Gutter 1 Ponding?

114.0 N/A Gutter 1 Lip Ht (In)

1.4 N/A Gutter 1 Slope (%)


Yes N/A DWS 1 Provided?

2.6 N/A Gutter 1 X Slope (%)



Possible Solutions: Remove & Replace Entire Refuge. Surveyor Notes: N/A

Total Cost: 3000.00



,, .	r antica / tranti.	.00	2	14//
N/A	X Walk 1 Direction	To N N/A	DWS 1 Contrast?	N/A
N/A	X Walk 1 Width (In)	105.0 N/A	DWS 1 Length (In)	N/A
N/A	Road 1 Slope (%)	0.8 N/A	DWS 1 Full Width?	N/A
N/A	Road 1 X Slope (%)	1.2 N/A	DWS 1 Offset (In)	N/A
Yes	Refuge 2 Length (In)	36.0 N/A	Gutter 2 Ponding?	N/A
Yes	Refuge 2 Width (In)	114.0 N/A	Gutter 2 Lip Ht (In)	N/A
Yes	Refuge 2 Slope (%)	0.0 N/A	Gutter 2 Slope (%)	N/A
Yes	Refuge 2 X Slope (%)	0.0 N/A	Gutter 2 X Slope (%)	N/A
N/A	Painted X Walk2?	Yes N/A	DWS 2 Provided?	N/A
N/A	X Walk 2 Direction	To S N/A	DWS 2 Contrast?	N/A
N/A	X Walk 2 Width (In)	106.0 N/A	DWS 2 Length (In)	N/A
N/A	Road 2 Slope (%)	2.2 N/A	DWS 2 Full Width?	N/A
N/A	Road 2 X Slope (%)	0.3 N/A	DWS 2 Offset (In)	N/A
N/A	Refuge 3 Length (in)	N/A N/A	Gutter 3 Ponding?	N/A
N/A	Refuge 3 Width (in)	N/A N/A	Gutter 3 Lip Ht (in)	N/A
N/A	Refuge 3 Slope (%)	N/A N/A	Gutter 3 Slope (%)	N/A
N/A	Refuge 3 XSlope (%)	N/A N/A	Gutter 3 XSlope (%)	N/A
N/A	Painted X Walk3?	No N/A	DWS 3 Provided?	N/A
N/A	X Walk 3 Direction	N/A N/A	DWS 3 Contrast?	N/A
N/A	X Walk 3 Width (in)	N/A N/A	DWS 3 Length (in)	N/A
N/A	Road 3 Slope (%)	N/A N/A	DWS 3 Full Width?	N/A
N/A	Road 3 XSlope (%)	N/A N/A	DWS 3 Offset (in)	N/A
Yes	Any Obstructions?	N/A N/A	Storm Grate/Utility Hazard?	N/A
N/A	Obstruction Type	N/A	Storm Grate/Utility Type	
		N/A		N/A
N/A	Surface Condition	Good		





