cole

Access Compliance Report Public Rights-of-Way (Island Curb Cuts)



Intersection ID: 13912 Main S	treet: KENILWORTH_AV	Cross	Street: E_JOHN_E	BELK RA	Location:	SE
			Pass/Fail: Fail	Overall Compliance:		47.5
		Innuari				47.0
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance			
	Possible Solutions:			ription Data Com		Data
Remove & Replace Entire Refuge.		-	Yes Refuge 1 Length		Gutter 1 Ponding?	N/A
a a subscription			Yes Refuge 1 Width (I		Gutter 1 Lip Ht (In)	N/A
Al Al and the second second			Yes Refuge 1 Slope (%		Gutter 1 Slope (%)	N/A
6.6.			Yes Refuge 1 X Slope		Gutter 1 X Slope (%)	N/A
A CHARLOTTETOWNE AV			N/A Painted X Walk1?		DWS 1 Provided?	N/A
	A		N/A X Walk 1 Direction		DWS 1 Contrast?	N/A
E JOHN EELK RA	Surveyor Notes:		N/A X Walk 1 Width (li		DWS 1 Length (In)	N/A
	N/A		N/A Road 1 Slope (%)	·	DWS 1 Full Width?	N/A
			N/A Road 1 X Slope ((%) 2.0 N/A	DWS 1 Offset (In)	N/A
			Yes Refuge 2 Length	(In) 37.0 N/A	Gutter 2 Ponding?	N/A
			Yes Refuge 2 Width (I	(In) 96.0 N/A	Gutter 2 Lip Ht (In)	N/A
			No Refuge 2 Slope (%	(%) 5.2 N/A	Gutter 2 Slope (%)	N/A
	PROW/ADA:		Yes Refuge 2 X Slope	e (%) 2.3 N/A	Gutter 2 X Slope (%)	N/A
	N/A		N/A Painted X Walk2?	? Yes N/A	DWS 2 Provided?	N/A
			N/A X Walk 2 Direction	on To SW N/A	DWS 2 Contrast?	N/A
			N/A X Walk 2 Width (I	ln) 117.0 N/A	DWS 2 Length (In)	N/A
	-		N/A Road 2 Slope (%)		DWS 2 Full Width?	N/A
			N/A Road 2 X Slope (DWS 2 Offset (In)	N/A
			Yes Refuge 3 Length ((in) 195.0 N/A	Gutter 3 Ponding?	N/A
	Total Cost: \$ 300		Yes Refuge 3 Width (in		Gutter 3 Lip Ht (in)	N/A
			Yes Refuge 3 Slope (%		Gutter 3 Slope (%)	N/A
			Yes Refuge 3 XSlope		Gutter 3 XSlope (%)	N/A
			N/A Painted X Walk3?		DWS 3 Provided?	N/A
			N/A X Walk 3 Direction		DWS 3 Contrast?	N/A
			N/A X Walk 3 Width (in		DWS 3 Length (in)	N/A
			N/A Road 3 Slope (%)		DWS 3 Full Width?	N/A
			N/A Road 3 XSlope (%)		DWS 3 Offset (in)	N/A
			Yes Any Obstructions	· · · · · · · · · · · · · · · · · · ·	Storm Grate/Utility Hazard?	N/A
			N/A Obstruction Type		Storm Grate/Utility Type	
				N/A		N/A
			N/A Surface Condition			100