

Access Compliance Report Public Rights-of-Way (Island Curb Cuts)



Data

N/A

Intersection ID: 15460 Main Street: CLANTON RD Cross Street: S I-77 TO CLANTON RD RA SB Location: S ADA ID: 5B47482906F9 Curb Cut Type: IslandRefuge3 Initial Pass/Fail: Fail **Overall Compliance: No** Severity Score: 36.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

60.0 N/A

4.2 N/A

N/A

Yes

109.0 N/A

70.0 N/A

60.0 N/A

2.1 N/A

Yes N/A

110.5 N/A

To NE

To SE

Data Compliance

91.0 N/A Gutter 1 Ponding?

Gutter 1 Lip Ht (In)

Gutter 1 Slope (%)

DWS 1 Provided?

DWS 1 Contrast?

DWS 1 Length (In)

DWS 1 Full Width?

Gutter 2 Ponding?

Gutter 2 Lip Ht (In)

Gutter 2 Slope (%)

DWS 2 Provided?

DWS 2 Contrast?

DWS 2 Length (In)

DWS 2 Full Width?

N/A Storm Grate/Utility Type


1.0 N/A DWS 2 Offset (In)

Gutter 2 X Slope (%)

3.0 N/A DWS 1 Offset (In)

Gutter 1 X Slope (%)

Description



Remove & Replace Entire Refuge.

Surveyor Notes:

Possible Solutions:

N/A

PROW/ADA:

N/A

Com	pliance Description	n
Yes	Refuge 1 Length (In)	
Yes	Refuge 1 Width (In)	
Yes	Refuge 1 Slope (%)	
Yes	Refuge 1 X Slope (%)	
N/A	Painted X Walk1?	
N/A	X Walk 1 Direction	
N/A	X Walk 1 Width (In)	
N/A	Road 1 Slope (%)	
N/A	Road 1 X Slope (%)	
Yes	Refuge 2 Length (In)	
Yes	Refuge 2 Width (In)	
Yes	Refuge 2 Slope (%)	
Yes	Refuge 2 X Slope (%)	
N/A	Painted X Walk2?	
N/A	X Walk 2 Direction	
N/A	X Walk 2 Width (In)	
N/A	Road 2 Slope (%)	
N/A	Road 2 X Slope (%)	
Yes	Refuge 3 Length (in)	

Obstruction Type

Surface Condition

Total Cost: 3000.00



N/A

Good





