

## Access Compliance Report Public Rights-of-Way (Island Curb Cuts)



Data

N/A

Intersection ID: 46602 Main Street: PARK\_RD\_SHOPPING\_CENTERCROSS Street: PARK\_RD Location: S

ADA ID: 5D00542D7DB3 Curb Cut Type: MedianRefuge2 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 1.25

Compliance

Description

Refuge 1 Length (In)

Refuge 1 Width (In)

X Walk 3 Direction

X Walk 3 Width (in)

Road 3 Slope (%)

Road 3 XSlope (%)

Any Obstructions?

Obstruction Type

Surface Condition

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

47.5 N/A

94.0 N/A

Data Compliance

Description

Gutter 1 Ponding?

Gutter 1 Lip Ht (In)



Possible Solutions:

Remove & Replace Entire Refuge.

Surveyor Notes:

N/A

PROW/ADA:

Total Cost:

N/A

Yes Refuge 1 Slope (%) 1.0 N/A Gutter 1 Slope (%) Gutter 1 X Slope (%) Refuge 1 X Slope (%) Painted X Walk1? DWS 1 Provided? N/A No DWS 1 Contrast? X Walk 1 Direction To E X Walk 1 Width (In) N/A DWS 1 Length (In) DWS 1 Full Width? Road 1 Slope (%) 1.8 N/A Road 1 X Slope (%) 2.0 N/A DWS 1 Offset (In) Refuge 2 Length (In) 47.5 N/A Gutter 2 Ponding? Yes Refuge 2 Width (In) Gutter 2 Lip Ht (In) 94.0 N/A Yes Refuge 2 Slope (%) Gutter 2 Slope (%) Refuge 2 X Slope (%) 0.3 N/A Gutter 2 X Slope (%) Yes N/A Painted X Walk2? No N/A DWS 2 Provided? To W DWS 2 Contrast? X Walk 2 Direction X Walk 2 Width (In) N/A N/A DWS 2 Length (In) Road 2 Slope (%) 0.6 DWS 2 Full Width? N/A DWS 2 Offset (In) Road 2 X Slope (%) 2.4 Refuge 3 Length (in) Gutter 3 Ponding? N/A Refuge 3 Width (in) N/A Gutter 3 Lip Ht (in) Gutter 3 Slope (%) N/A Refuge 3 Slope (%) N/A Refuge 3 XSlope (%) N/A Gutter 3 XSlope (%) Painted X Walk3? DWS 3 Provided? N/A N/A

N/A

N/A

N/A

N/A

N/A

Good

**DWS 3 Contrast?** 

DWS 3 Length (in)

DWS 3 Full Width?

DWS 3 Offset (in)

N/A Storm Grate/Utility Type

Storm Grate/Utility Hazard?







3000.00