

Access Compliance Report Public Rights-of-Way (Island Curb Cuts)



<u>Data</u>

N/A

N/A

Intersection ID: 28304 Main Street: LANCASTER_HY Cross Street: JOHNSTON_RD Location: N

ADA ID: 5E77D995BF1F Curb Cut Type: MedianRefuge2 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 13.75

Compliance

Description

Refuge 1 Length (In)

Refuge 1 Width (In)

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Data Compliance Description

156.5 N/A Gutter 1 Ponding?

119.0 N/A Gutter 1 Lip Ht (In)



Remove & Replace Entire Refuge.

Surveyor Notes: **N/A**

Possible Solutions:

PROW/ADA:

N/A

Total Cost: \$ 3000.00







Yes	Refuge 1 Slope (%)	3.4 N	/A	Gutter 1 Slope (%)	N/A
No	Refuge 1 X Slope (%)	5.4 N	/ A	Gutter 1 X Slope (%)	N/A
N/A	Painted X Walk1?	Yes N	/ A	DWS 1 Provided?	N/A
N/A	X Walk 1 Direction	To E N	/ A	DWS 1 Contrast?	N/A
N/A	X Walk 1 Width (In)	104.0 N	/ A	DWS 1 Length (In)	N/A
N/A	Road 1 Slope (%)	4.8 N	/ A	DWS 1 Full Width?	N/A
N/A	Road 1 X Slope (%)	4.4 N	/ A	DWS 1 Offset (In)	N/A
Yes	Refuge 2 Length (In)	15.5 N	/ A	Gutter 2 Ponding?	N/A
Yes	Refuge 2 Width (In)	119.0 N	/ A	Gutter 2 Lip Ht (In)	N/A
Yes	Refuge 2 Slope (%)	2.6 N	/ A	Gutter 2 Slope (%)	N/A
Yes	Refuge 2 X Slope (%)	3.0 N	/ A	Gutter 2 X Slope (%)	N/A
N/A	Painted X Walk2?	Yes N	/ A	DWS 2 Provided?	N/A
N/A	X Walk 2 Direction	To W N	/ A	DWS 2 Contrast?	N/A
N/A	X Walk 2 Width (In)	104.0 N	/ A	DWS 2 Length (In)	N/A
N/A	Road 2 Slope (%)	4.4 N	/ A	DWS 2 Full Width?	N/A
N/A	Road 2 X Slope (%)	2.5 N	/ A	DWS 2 Offset (In)	N/A
N/A	Refuge 3 Length (in)	N/A N	/ A	Gutter 3 Ponding?	N/A
N/A	Refuge 3 Width (in)	N/A N	/ A	Gutter 3 Lip Ht (in)	N/A
N/A	Refuge 3 Slope (%)	N/A N	/ A	Gutter 3 Slope (%)	N/A
N/A	Refuge 3 XSlope (%)	N/A N	/ A	Gutter 3 XSlope (%)	N/A
N/A	Painted X Walk3?	N/A N	/ A	DWS 3 Provided?	N/A
N/A	X Walk 3 Direction	N/A N	/ A	DWS 3 Contrast?	N/A
N/A	X Walk 3 Width (in)	N/A N	/ A	DWS 3 Length (in)	N/A
N/A	Road 3 Slope (%)	N/A N	/ A	DWS 3 Full Width?	N/A
N/A	Road 3 XSlope (%)	N/A N	/ A	DWS 3 Offset (in)	N/A
Yes	Any Obstructions?	N/A N	/ A	Storm Grate/Utility Hazard?	N/A
N/A	Obstruction Type	N	/ A	Storm Grate/Utility Type	
		N/A			N/A
N/A	Surface Condition	Good			