cole

Access Compliance Report Public Rights-of-Way (Island Curb Cuts)



| Intersection ID: 13197 | 197 Main Street: S_MCDOWELL_ST | | | Cross Street: E_4TH_ST | | | Location: NE | |
|---|---|--|----------------------------------|------------------------|------------------|--|-----------------------------|------|
| ADA ID: 5F186F87D72E Curb Cut Type: MedianRefuge2 | | Initial | nitial Pass/Fail: Fail Overall (| | Overall Complian | I Compliance: No Severity Se | | 0 |
| Codes/Mit | | Field | I Measurements/Co | omp | onent Compliance | | | |
| | Possible Solutions: | | Comp | oliance Descript | tion Data | Com | pliance Description | Data |
| | Remove & Replace Entire Refuge. | _ | Yes | Refuge 1 Length (In) |) 65.0 | N/A | Gutter 1 Ponding? | N/A |
| | | | | Refuge 1 Width (In) | | | Gutter 1 Lip Ht (In) | N/A |
| | 0 | | Yes | Refuge 1 Slope (%) | | | Gutter 1 Slope (%) | N/A |
| A CONTRACT OF | | | Yes | Refuge 1 X Slope (% | %) 3.8 | N/A | Gutter 1 X Slope (%) | N/A |
| 1 101 | | | N/A | Painted X Walk1? | Yes | N/A | DWS 1 Provided? | N/A |
| A PARA | un la | | N/A | X Walk 1 Direction | To SE | N/A | DWS 1 Contrast? | N/A |
| the termination | Surveyor Notes: | | N/A | X Walk 1 Width (In) | 146.0 | N/A | DWS 1 Length (In) | N/A |
| A COL | N/A | | N/A | Road 1 Slope (%) | 3.8 | N/A | DWS 1 Full Width? | N/A |
| S S | Ch. C. | | N/A | Road 1 X Slope (%) | 4.3 | N/A | DWS 1 Offset (In) | N/A |
| a k | Leo | | | | | | | |
| A A A A A A A A A A A A A A A A A A A | and the | | Yes | Refuge 2 Length (In) |) 65.0 | N/A | Gutter 2 Ponding? | N/A |
| | a the | | Yes | Refuge 2 Width (In) | 180.0 | N/A | Gutter 2 Lip Ht (In) | N/A |
| | | | Yes | Refuge 2 Slope (%) | 1.3 | N/A | Gutter 2 Slope (%) | N/A |
| | PROW/ADA: | | Yes | Refuge 2 X Slope (% | %) 3.8 | N/A | Gutter 2 X Slope (%) | N/A |
| the second second | N/A | | N/A | Painted X Walk2? | Yes | N/A | DWS 2 Provided? | N/A |
| | | | N/A | X Walk 2 Direction | To NW | N/A | DWS 2 Contrast? | N/A |
| | | | N/A | X Walk 2 Width (In) | 148.0 | N/A | DWS 2 Length (In) | N/A |
| | | | N/A | Road 2 Slope (%) | 4.3 | N/A | DWS 2 Full Width? | N/A |
| | | | N/A | Road 2 X Slope (%) | 0.7 | N/A | DWS 2 Offset (In) | N/A |
| | | | N/A | Refuge 3 Length (in) |) N/A | N/A | Gutter 3 Ponding? | N/A |
| | Total Cost: \$ 300 | 00.00 | N/A | Refuge 3 Width (in) | N/A | N/A | Gutter 3 Lip Ht (in) | N/A |
| | | | N/A | Refuge 3 Slope (%) | N/A | N/A | Gutter 3 Slope (%) | N/A |
| | | | N/A | Refuge 3 XSlope (%) | b) N/A | N/A | Gutter 3 XSlope (%) | N/A |
| | | | N/A | Painted X Walk3? | N/A | N/A | DWS 3 Provided? | N/A |
| | | and in | N/A | X Walk 3 Direction | N/A | N/A | DWS 3 Contrast? | N/A |
| | | | N/A | X Walk 3 Width (in) | N/A | N/A | DWS 3 Length (in) | N/A |
| | | - | N/A | Road 3 Slope (%) | N/A | N/A | DWS 3 Full Width? | N/A |
| | | | N/A | Road 3 XSlope (%) | N/A | N/A | DWS 3 Offset (in) | N/A |
| | | 1 | Yes | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| 1n | | | N/A | Obstruction Type | | N/A | Storm Grate/Utility Type | |
| | | a de la companya de l | | | N/A | | | N/A |
| | | | N/A | Surface Condition | Good | | | |