



Access Compliance Report

Public Rights-of-Way

(Island Curb Cuts)

Intersection ID: 44555	Main Street: UNIVERSITY_CITY_BV	Cross Street: N_TRYON_ST	Location:	W
ADA ID: 6C2F84AED502	Curb Cut Type: MedianRefuge2	Initial Pass/Fail: Pass	Overall Compliance: No	Severity Score: 12.5

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Detectable Warning System. Grind Gutter Lip. Remove & Replace Gutter.		Yes	Refuge 1 Length (In)	82.5
			Yes	Refuge 1 Width (In)	122.0
			Yes	Refuge 1 Slope (%)	0.3
			Yes	Refuge 1 X Slope (%)	1.3
			N/A	Painted X Walk1?	Yes
			N/A	X Walk 1 Direction	To S
			N/A	X Walk 1 Width (In)	117.0
			N/A	Road 1 Slope (%)	1.9
			N/A	Road 1 X Slope (%)	0.1
<p>Surveyor Notes:</p> <p>N/A</p>			Yes	Refuge 2 Length (In)	82.5
			Yes	Refuge 2 Width (In)	122.0
			Yes	Refuge 2 Slope (%)	1.3
			Yes	Refuge 2 X Slope (%)	1.1
			N/A	Painted X Walk2?	Yes
			N/A	X Walk 2 Direction	To N
			N/A	X Walk 2 Width (In)	130.0
			N/A	Road 2 Slope (%)	1.4
			N/A	Road 2 X Slope (%)	1.3
			N/A	Refuge 3 Length (in)	N/A
<p>PROW/ADA:</p> <p>N/A</p>			No	Gutter 1 Ponding?	Yes
			No	Gutter 1 Lip Ht (In)	0.5
			Yes	Gutter 1 Slope (%)	2.8
			No	Gutter 1 X Slope (%)	4.1
			Yes	DWS 1 Provided?	Yes
			Yes	DWS 1 Contrast?	Yes
			No	DWS 1 Length (In)	23.5
			No	DWS 1 Full Width?	No
			Yes	DWS 1 Offset (In)	0.0
			No	Gutter 2 Ponding?	Yes
<p>Total Cost:</p> <p>\$ 2550.00</p>			No	Gutter 2 Lip Ht (In)	0.25
			Yes	Gutter 2 Slope (%)	0.2
			Yes	Gutter 2 X Slope (%)	0.2
			Yes	DWS 2 Provided?	Yes
			Yes	DWS 2 Contrast?	Yes
			Yes	DWS 2 Length (In)	24.0
			No	DWS 2 Full Width?	No
			Yes	DWS 2 Offset (In)	0.0
			N/A	Gutter 3 Ponding?	No
			N/A	Gutter 3 Lip Ht (in)	N/A
			N/A	Gutter 3 Slope (%)	N/A
			N/A	Gutter 3 XSlope (%)	N/A
			No	DWS 3 Provided?	N/A
			N/A	DWS 3 Contrast?	N/A
			N/A	DWS 3 Length (in)	N/A
			N/A	DWS 3 Full Width?	N/A
			N/A	DWS 3 Offset (in)	N/A
			No	Storm Grate/Utility Hazard?	No
			N/A	Storm Grate/Utility Type	N/A
			N/A	Surface Condition	Good