



Access Compliance Report

Public Rights-of-Way

(Island Curb Cuts)

Intersection ID: 7951	Main Street: BEATTIES_FORD_RD	Cross Street: HOLLY_ST	Location:	N
ADA ID: 6FA6F7456081	Curb Cut Type: MedianRefuge2	Initial Pass/Fail: Pass	Overall Compliance: No	Severity Score: 0.25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Detectable Warning System.		Yes	Refuge 1 Length (In)	54.0
			Yes	Refuge 1 Width (In)	72.0
<p>Surveyor Notes:</p> <p>N/A</p>			Yes	Refuge 1 Slope (%)	4.9
			Yes	Refuge 1 X Slope (%)	0.4
			N/A	Painted X Walk1?	No
<p>PROW/ADA:</p> <p>N/A</p>			N/A	X Walk 1 Direction	To E
			N/A	X Walk 1 Width (In)	N/A
			N/A	Road 1 Slope (%)	0.7
<p>Total Cost:</p> <p>\$ 1600.00</p>			N/A	Road 1 X Slope (%)	3.5
			Yes	Refuge 2 Length (In)	54.0
			Yes	Refuge 2 Width (In)	72.0
			Yes	Refuge 2 Slope (%)	3.3
			Yes	Refuge 2 X Slope (%)	0.6
			N/A	Painted X Walk2?	No
			N/A	X Walk 2 Direction	To W
			N/A	X Walk 2 Width (In)	N/A
			N/A	Road 2 Slope (%)	0.4
			N/A	Road 2 X Slope (%)	1.7
			N/A	Refuge 3 Length (in)	N/A
			N/A	Refuge 3 Width (in)	N/A
			N/A	Refuge 3 Slope (%)	N/A
			N/A	Refuge 3 XSlope (%)	N/A
			N/A	Painted X Walk3?	N/A
			N/A	X Walk 3 Direction	N/A
			N/A	X Walk 3 Width (in)	N/A
			N/A	Road 3 Slope (%)	N/A
			N/A	Road 3 XSlope (%)	N/A
			Yes	Any Obstructions?	No
			N/A	Obstruction Type	N/A
			N/A		N/A
			N/A	Surface Condition	Good