

## Access Compliance Report Public Rights-of-Way (Island Curb Cuts)



<u>Data</u>

No

0.0

1.4

Intersection ID: 14340 Main Street: KENILWORTH\_AV Cross Street: GREENWOOD\_CLIFF Location: NE
ADA ID: 76EEFC08C6B3 Curb Cut Type: MedianRefuge2 Initial Pass/Fail: Pass Overall Compliance: Yes Severity Score: 0

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Possible Solutions:

Compliance Description

Data Compliance Description

Yes Refuge 1 Length (In)

Refuge 1 Width (In)

Refuge 1 Slope (%)

Refuge 1 X Slope (%)



Possible Solutions:

Surveyor Notes:

N/A

PROW/ADA:

N/A

Total Cost: \$ 0.00







|     | ,                    |       |     |                             |      |
|-----|----------------------|-------|-----|-----------------------------|------|
| N/A | Painted X Walk1?     | No    | Yes | DWS 1 Provided?             | Yes  |
| N/A | X Walk 1 Direction   | To NW | Yes | DWS 1 Contrast?             | Yes  |
| N/A | X Walk 1 Width (In)  | N/A   | Yes | DWS 1 Length (In)           | 25.0 |
| N/A | Road 1 Slope (%)     | 1.5   | Yes | DWS 1 Full Width?           | Yes  |
| N/A | Road 1 X Slope (%)   | 3.7   | Yes | DWS 1 Offset (In)           | 0.0  |
|     |                      |       |     |                             |      |
| Yes | Refuge 2 Length (In) | 43.0  | Yes | Gutter 2 Ponding?           | No   |
| Yes | Refuge 2 Width (In)  | 96.0  | Yes | Gutter 2 Lip Ht (In)        | 0.0  |
| Yes | Refuge 2 Slope (%)   | 1.2   | Yes | Gutter 2 Slope (%)          | 2.8  |
| Yes | Refuge 2 X Slope (%) | 1.5   | Yes | Gutter 2 X Slope (%)        | 1.8  |
| N/A | Painted X Walk2?     | No    | Yes | DWS 2 Provided?             | Yes  |
| N/A | X Walk 2 Direction   | To SE | Yes | DWS 2 Contrast?             | Yes  |
| N/A | X Walk 2 Width (In)  | N/A   | Yes | DWS 2 Length (In)           | 25.0 |
| N/A | Road 2 Slope (%)     | 2.0   | Yes | DWS 2 Full Width?           | Yes  |
| N/A | Road 2 X Slope (%)   | 0.1   | Yes | DWS 2 Offset (In)           | 0.0  |
|     |                      |       |     |                             |      |
| N/A | Refuge 3 Length (in) | N/A   | N/A | Gutter 3 Ponding?           | N/A  |
| N/A | Refuge 3 Width (in)  | N/A   | N/A | Gutter 3 Lip Ht (in)        | N/A  |
| N/A | Refuge 3 Slope (%)   | N/A   | N/A | Gutter 3 Slope (%)          | N/A  |
| N/A | Refuge 3 XSlope (%)  | N/A   | N/A | Gutter 3 XSlope (%)         | N/A  |
| N/A | Painted X Walk3?     | N/A   | N/A | DWS 3 Provided?             | N/A  |
| N/A | X Walk 3 Direction   | N/A   | N/A | DWS 3 Contrast?             | N/A  |
| N/A | X Walk 3 Width (in)  | N/A   | N/A | DWS 3 Length (in)           | N/A  |
| N/A | Road 3 Slope (%)     | N/A   | N/A | DWS 3 Full Width?           | N/A  |
| N/A | Road 3 XSlope (%)    | N/A   | N/A | DWS 3 Offset (in)           | N/A  |
| Yes | Any Obstructions?    | N/A   | N/A | Storm Grate/Utility Hazard? | No   |
| N/A | Obstruction Type     |       | N/A | Storm Grate/Utility Type    |      |
|     |                      | N/A   |     |                             | N/A  |
| N/A | Surface Condition    | Good  | J   |                             |      |
|     |                      |       |     |                             |      |
|     |                      |       |     |                             |      |

**43.0 Yes** Gutter 1 Ponding?

96.0 Yes Gutter 1 Lip Ht (In)

**1.1 Yes** Gutter 1 Slope (%)

**1.9 Yes** Gutter 1 X Slope (%)