

Access Compliance Report Public Rights-of-Way (Island Curb Cuts)



Data

N/A

Intersection ID: 53165Main Street: DIXIE_RIVER_RDCross Street: STYLE_LNLocation:NADA ID: 773F5A3E4E02Curb Cut Type: MedianRefuge2Initial Pass/Fail: FailOverall Compliance: NoSeverity Score:0

Compliance

N/A

Description

Refuge 1 Length (In)

Refuge 1 Width (In)

Refuge 1 Slope (%)

Painted X Walk1?

X Walk 1 Direction

X Walk 1 Width (In)

Road 1 Slope (%)

Road 1 X Slope (%)

Refuge 2 Length (In)

Refuge 2 Width (In)

Refuge 1 X Slope (%)

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Yes N/A

To W N/A

102 N/A

Data Compliance

102 N/A Gutter 1 Ponding?

114 N/A Gutter 1 Lip Ht (In)

0.3 N/A Gutter 1 Slope (%)

112 N/A DWS 1 Length (In)

4.1 N/A DWS 1 Offset (In)

3.5 N/A Gutter 1 X Slope (%)

DWS 1 Provided?

DWS 1 Contrast?

DWS 1 Full Width?

Gutter 2 Ponding?

Gutter 2 Lip Ht (In)

Description



Remove & Replace Entire Refuge.

Surveyor Notes:

N/A

Possible Solutions:

PROW/ADA:

N/A

N/A 00.00 N/A

Total Cost: \$ 3000.00







162	Reluge 2 Width (III)	114	IN/A	Gutter 2 Lip Ht (III)	IN/A
Yes	Refuge 2 Slope (%)	0.3	N/A	Gutter 2 Slope (%)	N/A
Yes	Refuge 2 X Slope (%)	4.6	N/A	Gutter 2 X Slope (%)	N/A
N/A	Painted X Walk2?	N/A	N/A	DWS 2 Provided?	N/A
N/A	X Walk 2 Direction	To NE	N/A	DWS 2 Contrast?	N/A
N/A	X Walk 2 Width (In)	111	N/A	DWS 2 Length (In)	N/A
N/A	Road 2 Slope (%)	6.0	N/A	DWS 2 Full Width?	N/A
N/A	Road 2 X Slope (%)	1.8	N/A	DWS 2 Offset (In)	N/A
N/A	Refuge 3 Length (in)	N/A	N/A	Gutter 3 Ponding?	N/A
N/A	Refuge 3 Width (in)	N/A	N/A	Gutter 3 Lip Ht (in)	N/A
N/A	Refuge 3 Slope (%)	N/A	N/A	Gutter 3 Slope (%)	N/A
N/A	Refuge 3 XSlope (%)	N/A	N/A	Gutter 3 XSlope (%)	N/A
N/A	Painted X Walk3?	N/A	N/A	DWS 3 Provided?	N/A
N/A	X Walk 3 Direction	N/A	N/A	DWS 3 Contrast?	N/A
N/A	X Walk 3 Width (in)	N/A	N/A	DWS 3 Length (in)	N/A
N/A	Road 3 Slope (%)	N/A	N/A	DWS 3 Full Width?	N/A
N/A	Road 3 XSlope (%)	N/A	N/A	DWS 3 Offset (in)	N/A
Yes	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
N/A	Obstruction Type		N/A	Storm Grate/Utility Type	
		N/A			N/A
N/A	Surface Condition	N/A			