


Access Compliance Report Public Rights-of-Way (Island Curb Cuts)

Intersection ID: 5966	Main Street: SUNSTONE_DR	Cross Street: STATESVILLE_RD	Location: N
ADA ID: 794988D32590	Curb Cut Type: MedianRefuge2	Initial Pass/Fail: Pass	Overall Compliance: No Severity Score: 7.75

Codes/Mitigation Info/Possible Solution	Field Measurements/Component Compliance
---	---



Possible Solutions:
**Remove & Replace Entire Refuge.
Grind Gutter Lip.**

Surveyor Notes:
N/A

PROW/ADA:
N/A

Total Cost: \$ **3400.00**



Compliance	Description	Data	Compliance	Description	Data
No	Refuge 1 Length (In)	35.5	No	Gutter 1 Ponding?	Yes
Yes	Refuge 1 Width (In)	95.5	No	Gutter 1 Lip Ht (In)	0.5
Yes	Refuge 1 Slope (%)	1.6	Yes	Gutter 1 Slope (%)	1.9
Yes	Refuge 1 X Slope (%)	1.4	Yes	Gutter 1 X Slope (%)	1.0
N/A	Painted X Walk1?	No	No	DWS 1 Provided?	Yes
N/A	X Walk 1 Direction	To W	N/A	DWS 1 Contrast?	Yes
N/A	X Walk 1 Width (In)	N/A	N/A	DWS 1 Length (In)	24.0
N/A	Road 1 Slope (%)	1.0	N/A	DWS 1 Full Width?	Yes
N/A	Road 1 X Slope (%)	0.8	N/A	DWS 1 Offset (In)	0.0
No	Refuge 2 Length (In)	35.5	No	Gutter 2 Ponding?	Yes
Yes	Refuge 2 Width (In)	95.5	No	Gutter 2 Lip Ht (In)	0.5
Yes	Refuge 2 Slope (%)	2.9	Yes	Gutter 2 Slope (%)	3.0
Yes	Refuge 2 X Slope (%)	0.7	Yes	Gutter 2 X Slope (%)	1.6
N/A	Painted X Walk2?	No	No	DWS 2 Provided?	Yes
N/A	X Walk 2 Direction	To NE	N/A	DWS 2 Contrast?	Yes
N/A	X Walk 2 Width (In)	N/A	N/A	DWS 2 Length (In)	24.0
N/A	Road 2 Slope (%)	1.0	N/A	DWS 2 Full Width?	Yes
N/A	Road 2 X Slope (%)	2.7	N/A	DWS 2 Offset (In)	0.0
N/A	Refuge 3 Length (in)	N/A	N/A	Gutter 3 Ponding?	No
N/A	Refuge 3 Width (in)	N/A	N/A	Gutter 3 Lip Ht (in)	N/A
N/A	Refuge 3 Slope (%)	N/A	N/A	Gutter 3 Slope (%)	N/A
N/A	Refuge 3 XSlope (%)	N/A	N/A	Gutter 3 XSlope (%)	N/A
N/A	Painted X Walk3?	No	N/A	DWS 3 Provided?	N/A
N/A	X Walk 3 Direction	N/A	N/A	DWS 3 Contrast?	N/A
N/A	X Walk 3 Width (in)	N/A	N/A	DWS 3 Length (in)	N/A
N/A	Road 3 Slope (%)	N/A	N/A	DWS 3 Full Width?	N/A
N/A	Road 3 XSlope (%)	N/A	N/A	DWS 3 Offset (in)	N/A
Yes	Any Obstructions?	No	N/A	Storm Grate/Utility Hazard?	No
N/A	Obstruction Type		N/A	Storm Grate/Utility Type	
			N/A		N/A
N/A	Surface Condition	Good			