cole

Access Compliance Report Public Rights-of-Way (Island Curb Cuts)



Intersection ID: 16151	Main Street: FREELAND_LN			Cross Street: S_TRYON_ST			SW
ADA ID: 7A38D31C2FE7 Curb Cut Type: MedianRefuge2			Pass	s/Fail: Fail Ove	arall Compliance	: No Severity Score:	0
Codes/M		Field Measurements/Component Compliance					
	Possible Solutions:		Com	pliance Description	Data Con		Data
BAR B	Remove & Replace Entire Refuge	د	No	Refuge 1 Length (In)		Gutter 1 Ponding?	N/A
	risinovo a rispiaco Entro ristage		Yes	Refuge 1 Width (In)		Gutter 1 Lip Ht (In)	N/A
Sansa Marina			Yes	Refuge 1 Slope (%)	0.3 N/A		N/A
Contra de la	A MA		Yes	Refuge 1 X Slope (%)	2.6 N/A		N/A
	G. A.		N/A	Painted X Walk1?	No N/A		N/A
	E C		N/A	X Walk 1 Direction	To SE N/A	DWS 1 Contrast?	N/A
A A A A A A A A A A A A A A A A A A A	Surveyor Notes:		N/A	X Walk 1 Width (In)	N/A N/A		N/A
	N/A		N/A	Road 1 Slope (%)	3.6 N/A		N/A
	19 lan		N/A	Road 1 X Slope (%)	3.9 N/A	DWS 1 Offset (In)	N/A
				,		· · /	
S 1 5			No	Refuge 2 Length (In)	31.0 N/A	Gutter 2 Ponding?	N/A
1 0 0 m			Yes	Refuge 2 Width (In)	122.0 N/A	-	N/A
3/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1			Yes	Refuge 2 Slope (%)	1.9 N/A		N/A
	PROW/ADA:		Yes	Refuge 2 X Slope (%)	1.6 N/A		N/A
	N/A		N/A	Painted X Walk2?	No N/A	DWS 2 Provided?	N/A
	and the second sec		N/A	X Walk 2 Direction	To NW N/A	DWS 2 Contrast?	N/A
			N/A	X Walk 2 Width (In)	N/A N/A	DWS 2 Length (In)	N/A
			N/A	Road 2 Slope (%)	4.2 N/A	DWS 2 Full Width?	N/A
			N/A	Road 2 X Slope (%)	3.9 N/A	DWS 2 Offset (In)	N/A
			N/A	Refuge 3 Length (in)	N/A N/A	Gutter 3 Ponding?	N/A
	Total Cost: \$ 3	00.00	N/A	Refuge 3 Width (in)	N/A N/A	Gutter 3 Lip Ht (in)	N/A
			N/A	Refuge 3 Slope (%)	N/A N/A	Gutter 3 Slope (%)	N/A
			N/A	Refuge 3 XSlope (%)	N/A N/A	Gutter 3 XSlope (%)	N/A
			N/A	Painted X Walk3?	N/A N/A	DWS 3 Provided?	N/A
		Carriel Carly	N/A	X Walk 3 Direction	N/A N/A	DWS 3 Contrast?	N/A
		Soft	N/A	X Walk 3 Width (in)	N/A N/A	DWS 3 Length (in)	N/A
				Road 3 Slope (%)	N/A N/A	DWS 3 Full Width?	N/A
				Road 3 XSlope (%)	N/A N/A	DWS 3 Offset (in)	N/A
A A A A A A A A A A A A A A A A A A A		and the second s		Any Obstructions?		Storm Grate/Utility Hazard?	N/A
			N/A	Obstruction Type	N/A	Storm Grate/Utility Type	
					N/A		N/A
			N/A	Surface Condition	Good		